

പരിമുന്നാം കേരള നിയമസഭ

പരിനാലാം സമ്മേളനം

നക്ഷത്ര ചിഹ്നമിടാത്ത ചോദ്യം നമ്പർ: 4927

24.07.15 -ൽ

മറ്റപടികൾ

കയ്പമംഗലം നിയോജക മണ്ഡലത്തിലെ കടൽഭിത്തി നിർമ്മാണ പ്രവൃത്തികൾ

ചോദ്യം

ഉത്തരം

എ.വി.എസ്.സുനിൽ കുമാർ

എ.പി.ജെ.ജോസഫ്

(ജലവിഭവ വകുപ്പുമന്ത്രി)

- | | |
|--|--|
| (എ) കയ്പമംഗലം
മണ്ഡലത്തിലെ
നിർമ്മാണ
ഭരണാനുമതി
പ്രാപ്നാസൽ ലഭിച്ചിട്ടുണ്ടോ; | നിയോജക
കടൽഭിത്തി
പ്രവൃത്തികൾക്ക്
നൽകുന്നതിനായുള്ള
പ്രാപ്നാസൽ ലഭിച്ചിട്ടുണ്ടോ; |
| (ബി) കടൽഭിത്തി
പ്രവൃത്തികൾക്ക്
ലഭിക്കുന്നതിനായുള്ള
സർക്കാരിൽ ലഭിച്ചിട്ടുണ്ടോ; | പുനർന്നിർമ്മാണ
ഭരണാനുമതി
പ്രാപ്നാസൽ |
| (സി) എക്കിൽ പ്രസ്തുത പ്രവൃത്തികൾ
എത്രാക്കൈയെന്ന് വ്യക്തമാക്കുമോ; | |
| (ഡി) പ്രസ്തുത പ്രവൃത്തികൾക്ക് ആവശ്യമായ
പണം വകയിൽത്തി ഭരണാനുമതി
നൽകുന്നതിന്
സ്വീകരിക്കുമോ? | നിയോജക
കടൽഭിത്തി നിർമ്മാണ
പ്രവൃത്തികളുടെ
തയ്യാറാക്കിട്ടുണ്ട്.
&
(ഡി) അനുബന്ധമായി ചേർത്തിരിക്കുന്നു
ഇതിന്റെ വിശദമായ എസ്സിലേറ്റ് വകുപ്പ്
തലത്തിൽ തയ്യാറാക്കി വരുന്നു. |

സെക്രഡറി ഓഫീസർ

(2)

Panchayat Works

LIST OF PANE WORKS UNDER ADDITIONAL IRRIGATION DIVISION, TIRISSUR

(15 NOV 8)

Kodungallur Taluk

Sl No.	Name of work	Amount in Lakhs
1	ASE- Urgent reformation works to the damaged sea wall for a length of 460m between CP 3960 and 3963 in Mathilakam panchayath in Kodungallur Taluk	175.00
2	ASE- Constructing sea wall for a length of 150m (including return wall)between CP 3962 & 3964 in Mathilakam panchayath in Kodungallur Taluk (from 65m south of CP 3962 towards south)	90.00
3	ASE- Urgent reformation works to the damaged sea wall for a length of 110m towards north of CP 3980 at Anchangadi in SN Puram Panchayath in Kodungallur Taluk	55.00
4	ASE- Constructing sea wall for a length of 250m (including return wall) at Puthiya road fishing gap between CP 3993 and 3994 in Kodungallur Taluk	160.00
5	ASE- Urgent reformation works to the damaged sea wall for a length of 668m from south of CP 3994 to3997 at north of Manapattuchal in Eriyad panchayath in Kodungallur Taluk.	303.00
6	ASE- Urgent reformation works to the damaged sea wall for a length of 873m (including return wall) from south of CP 3997 and 4002 in Eriyad panchayath in Kodungallur Taluk.	386.00
7	ASE- Urgent reformation works to the damaged sea wall for a length of 635m between CP 3963 and 3966 at Pokklai in Mathilakam pauchayath in Kodungallur Taluk.(from 65m south of CP 3963 towards south)	250.00
8	ASE- Urgent reformation works to the damaged sea wall for a length of 885m (including return wall at north side of Vaakadappuram fishing gap)between CP 3984 and 3988 at Kara in Edavilangu panchayath in Kodungallur Taluk.	355.00
9	ASE- Urgent reformation works to the damaged sea wall for a length of 880m from south side return of Vaakadappuram to north side of Puthiya Road Arappa between CP 3988 and 3993 at Kara in Edavilangu panchayath in Kodungallur Taluk.	410.00
10	ASE- Urgent reformation works to the damaged sea wall for a length of 100m towards sorth of CP 3968 at Vekkode in SN Puram Panchayath in Kodungallur Taiuk	50.00

11	ASE- Urgent reformation works to the damaged sea wall for a length of 150m from Ch.75m towards south of CP 3971 at vekkode in SN Puram Panchayath in Kodungallur Taluk	75.00
12	ASE- Urgent reformation works to the damaged sea wall for a length of 198m between CP 3947 & 3950 and starts from 90m North of CP 3949 for a length of 198 m including returns in Perinjanam Panchayath in Kodungallur Taluk	95.00
13	ASE- Urgent reformation works to the damaged sea wall for a length of 150m between CP 3950 & 3951 and starts from North of CP 3951 in Perifjanam Panchayath in Kodungallur Taluk	68.00
14	ASE- Urgent reformation works to the damaged sea wall between 0 to 75m towards South of CP 3957 in Perinjanam Panchayath in Kodungallur Taluk	50.00
15	ASE- Uregent reformation works to the damaged sea wall for a length of 40m between CP 3956 & 3957 in Mathilakam Panchayath in Kodungallur Taluk	25.00
16	ASE- Uregent reformation works to the damaged sea wall for a length of 40m between CP 3956 & 3957 in Mathilakam Panchayath in Kodungallur Taluk	25.00

**PROPOSALS OF ASE WORKS UNDER ADDITIONAL IRRIGATION DIVISION,THRISSUR
(13 nos)**

No.	Name of work	Amount in Lakhs
1	ASE- Urgent reformation works to the damaged sea wall for a length of 460m between CP 3960 and 3963 in Mathilakam panchayath in Kodungallur Taluk	175.00
2	ASE- Urgent reformation works to the damaged sea wall for a length of 110m towards north of CP 3980 at Anchangadi in SN Puram Panchayath in Kodungallur Taluk	55.00
3	ASE- Urgent reformation works to the damaged sea wall for a length of 668m from south of CP 3994 to 3997 at north of Manapattuchal in Eriyad panchayath in Kodungallur Taluk.	303.00
4	ASE- Urgent reformation works to the damaged sea wall for a length of 873m (including return wall) from south of CP 3997 and 4002 in Eriyad panchayath in Kodungallur Taluk.	386.00
5	ASE- Urgent reformation works to the damaged sea wall for a length of 635m between CP 3963 and 3966 at Pokklai in Mathilakam panchayath in Kodungallur Taluk.(from 65m south of CP 3963 towards south)	250.00
6	ASE- Urgent reformation works to the damaged sea wall for a length of 885m (including return wall at north side of Vaakadappuram fishing gap)between CP 3984 and 3988 at Kara in Edavilangu panchayath in Kodungallur Taluk.	355.00
7	ASE- Urgent reformation works to the damaged sea wall for a length of 880m from south side return of Vaakadappuram to north side of Puthiya Road Arappa between CP 3988 and 3993 at Kara in Edavilangu panchayath in Kodungallur Taluk.	410.00
8	ASE- Urgent reformation works to the damaged sea wall for a length of 100m towards sorth of CP 3968 at Vekkode in SN Puram Panchayath in Kodungallur Taluk	50.00
9	ASE- Urgent reformation works to the damaged sea wall for a length of 150m from Ch.75m towards south of CP 3971 at vekkode in SN Puram Panchayath in Kodungallur Taluk	75.00
10	ASE- Urgent reformation works to the damaged sea wall for a length of 198m between CP 3947 & 3950 and starts from 90m North of CP 3949 for a length of 198 m including returns in Perinjanam Panchayath in Kodungallur Taluk	35.00

(5)

11	ASE- Urgent reformation works to the damaged sea wall for a length of 150m between CP 3950 & 3951 and starts from North of CP 3951 in Perinjanam Panchayath in Kodungallur Taluk	68.00
12	ASE- Urgent reformation works to the damaged sea wall between 0 to 75m towards South of CP 3957 in Perinjanam Panchayath in Kodungallur Taluk	50.00
13	ASE- Urgent reformation works to the damaged sea wall for a length of 40m between CP 3956& 3957 in Mathilakam Panchayath in Kodungallur Taluk	25.00



SECTION OFFICER