

**15 -ാം കേരള നിയമസഭ**

**4 -ാം സമ്മേളനം**

**നക്ഷത്ര ചിഹ്നം ഇല്ലാത്ത ചോദ്യം നം. 951**

**24-02-2022 - ൽ മറുപടിയ്ക്ക്**

**കൊച്ചിൻ ഫ്രോണ്ടിയർ തോടിന്റെ നവീകരണം**

ചോദ്യം		ഉത്തരം	
<b>ശ്രീ. മുരളി പെരുന്നേല്ലി</b>		<b>Shri Roshy Augustine (ജലവിഭവ വകുപ്പ് മന്ത്രി)</b>	
(എ)	മണലൂർ മണ്ഡലത്തിലെ കൊച്ചിൻ ഫ്രോണ്ടിയർ തോടിന്റെ നവീകരണവുമായി ബന്ധപ്പെട്ട സർവ്വേ നടപടികളുടെ ഭാഗമായി അതിർത്തി നിർണ്ണയിച്ച് കല്ലുകൾ സ്ഥാപിക്കുന്നതിനായി എത്ര തുകയുടെ ഭരണാനുമതിയാണ് നൽകിയിട്ടുള്ളത്; ഭരണാനുമതി ഉത്തരവിന്റെ പകർപ്പ് ലഭ്യമാക്കാമോ;	(എ)	മണലൂർ മണ്ഡലത്തിലെ കൊച്ചിൻ ഫ്രോണ്ടിയർ തോടിന്റെ നവീകരണവുമായി ബന്ധപ്പെട്ട സർവ്വേ നടപടികളുടെ ഭാഗമായി അതിർത്തി നിർണ്ണയിച്ച് കല്ലുകൾ സ്ഥാപിക്കുന്നതിനായി 6,70,000/- രൂപയുടെ ഭരണാനുമതി നൽകിയിട്ടുണ്ട്. ഭരണാനുമതി ഉത്തരവിന്റെ പകർപ്പ് അനുബന്ധമായി ചേർക്കുന്നു.
(ബി)	പ്രസ്തുത സർവ്വേ നടപടികൾ നിലവിൽ ഏത് ഘട്ടത്തിലാണെന്ന് അറിയിക്കാമോ?	(ബി)	കോച്ചിൻ ഫ്രോണ്ടിയർ തോടിന്റെ ഏകദേശം 7 കി.മീ നീളം സർവ്വേ നടത്തുകയും അത്രയും ദൂരം സർവ്വേ കല്ലുകൾ സ്ഥാപിക്കുകയും ചെയ്തിട്ടുണ്ട്. തുടർന്നുള്ള 15 കി.മീ ദൂരം കൊച്ചിൻ ഫ്രോണ്ടിയർ തോടിന്റെ അതിർത്തി നിർണ്ണയവും അതിർത്തി കല്ല് സ്ഥാപിക്കുന്നതിനുമുള്ള നടപടികൾ സ്വീകരിച്ചുവരുന്നു.

സെക്ഷൻ ഓഫീസർ

*Boonamanoor*

EST NO:2019/4270/IA

ADMINISTRATIVE SANCTION FOR WORKS

PROCEEDINGS OF THE CHIEF ENGINEER IRRIGATION & ADMINISTRATION

PRESENT :Sri/Smt Shamsudeen KH

Sub- Site clearing and boundary stone fixing works for land surveying of Kochin frontier thodu in Kunnamkulam and Chavakkad taluks under Land records Tahsildar chavakkad

ORDER No. MIDTsr/2019/4270/IA      Dated: 04-06-2019

Administrative Sanction is hereby accorded for the Site clearing and boundary stone fixing works for land surveying of Kochin frontier thodu in Kunnamkulam and Chavakkad taluks under Land records Tahsildar chavakkad at an estimate cost of 670000 (Rupees Six Lakh Seventy Thousand).

The expenditure of this may be met from the provision under the head of account 2702-80-005-99-00-00-V (DETAILED INVESTIGATION OF MINOR IRRIGATION WORKS AND PREPARATION OF INTEGRATED PLANS)

Administrative Sanction issued for the above work is entered in the administrative sanction register vide register number 2913/2019-2020

-sd

Chief Engineer

Irri...  
P R O C E E D I N G S