

**പതിനാലാം കേരള നിയമസഭ
പതിമൂന്നാം സമ്മേളനം**

നക്ഷത്ര ചിഹ്നമിടാത്ത ചോദ്യം നം. 3093 10.12.2018 ൽ മറുപടിക്ക്

പാലക്കാട് ജില്ലയിൽ പ്രളയത്തിൽ ഉണ്ടായ നാശനഷ്ടങ്ങൾ

ചോദ്യം

ഉത്തരം

ശ്രീ.കെ.ഡി. പ്രസേനൻ

**ശ്രീ. ജി.സുധാകരൻ
(പൊതു മരാമത്തും രജിസ്ട്രേഷനും
വകുപ്പ് മന്ത്രി)**

എ) ഈ വർഷം ആഗസ്റ്റ് മാസത്തിൽ ഉണ്ടായ പ്രളയത്തിലും മണ്ണിടിച്ചിലിലും റോഡുകളും പാലങ്ങളും തകർന്ന് പാലക്കാട് ജില്ലയിൽ ഉണ്ടായ നാശനഷ്ടങ്ങളെക്കുറിച്ച് വിശദീകരിക്കാമോ?


എ),
ബി)
&
സി)

ഈ വർഷം ആഗസ്റ്റ് മാസത്തിൽ ഉണ്ടായ പ്രളയത്തിലും മണ്ണിടിച്ചിലിലും ദേശീയപാത 966 വേലിക്കാട് പാലത്തിന് ഏകദേശം നാല് ലക്ഷം രൂപയുടെ കേടുപാടുകൾ സംഭവിച്ചിട്ടുണ്ട്. പാലക്കാട് ജില്ലയിലെ നാട്ടുകൾ മുതൽ താണാവ് വരെയുള്ള ദേശീയപാത 966 ഹേവ്ഡ് ഷോൾഡറോടുകൂടിയ രണ്ടു വരിപ്പാതയായി ഇ.പി.സി. മോഡിൽ വികസിപ്പിക്കുന്ന പ്രവൃത്തി ഊരാളുങ്കൽ ലേബർ കോൺട്രാക്ട് കോ-ഓപ്പറേറ്റീവ് സൊസൈറ്റി ലിമിറ്റഡ് എന്ന കരാർ കമ്പനിയായാണ് ഏറ്റെടുത്ത് നടപ്പിലാക്കുന്നത്. പ്രസ്തുത കമ്പനി അറ്റകുറ്റപ്പണികൾ പൂർത്തീകരിച്ചിട്ടുണ്ട്. നിരത്തുവിഭാഗത്തിന്കീഴിൽ പ്രളയത്തിലും മണ്ണിടിച്ചിലിലും നെല്ലിയാമ്പതി റോഡിലെ ഒരു കല്ലുക തകർന്നിട്ടുണ്ട്. മാത്രമല്ല പാലക്കാട് ജില്ലയിൽ ആകെ 51 പാലങ്ങൾക്ക് അറ്റകുറ്റപ്പണികൾ ആവശ്യമായി വന്നിട്ടുണ്ട്. നിരത്തുവിഭാഗത്തിൽ ആകെ 22081.50 ലക്ഷം രൂപയുടെ നാശനഷ്ടങ്ങൾ സംഭവിച്ചിട്ടുണ്ട്. 51 പാലങ്ങളിൽ 49 പാലങ്ങൾക്ക് അറ്റകുറ്റപ്പണികൾക്കായി ഭരണാനുമതി നൽകിയിട്ടുണ്ട്.

ബി) എത്ര രൂപയുടെ നാശനഷ്ടങ്ങൾ ഉണ്ടാകുമെന്നാണ് കണക്കാക്കിയിട്ടുള്ളത്?

സി) നാശം നേരിട്ട റോഡുകളുടെയും പാലങ്ങളുടെയും അറ്റകുറ്റപ്പണികൾക്കായി എന്തെല്ലാം നടപടികൾ സ്വീകരിച്ചിട്ടുണ്ട് എന്ന് വ്യക്തമാക്കാമോ?

റോഡുകളുടെ അറ്റകുറ്റപ്പണികൾ സംബന്ധിച്ച വിശദാംശം അനുബന്ധമായി ചേർക്കുന്നു.


മന്ത്രി

LA-3093

2.

7	Palakad- Pollachi road	Culvert and Retaining wall collapsed 20/000	Work nearing completion
		Surface damaged 21/600 to 29/992	Work completed
8	Nattukal -Velamthavalam road	Culvert and Side protection collapsed 1/100,7/200	Work started
9	Chittur - Vandithavalm road (Shanmugham Cause way)	Hand rail damaged 1/200	Selection notice to be issued
10	Athikode - Palathulli road (Palathulli bridge)	Hand rail damaged 2/500	Selection notice to be issued
11	Pezhumpara- Maruthanchery road	Bridge approach surface damaged From km 0/950 to 1/050	Work started
		Water stagnation From Km 5/100 to 5/200	Work started
12	Palakkad- Pollachi Road km 5/00 -17/00.	Pot Holes Developed at km .5/00 -17/00.	Work completed
13	Palakkad Ponnani Road km. 0/00 - 8/00 (Except km 0/600 to 1/400)	Pot Holes Developed at km 0/00 - 8/00 (Except km 0/600 to 1/400)	Work completed
14	Kalmandapam - Kalpathy Road km. 0/000 - 1/500	Pot Holes Developed at km 0/000 - 1/500	Work completed
15	Olavakkode Malampuzha Road km 0/00 - 0/400.	Pot Holes Developed at km 0/00 - 0/400.	Work completed
16	GVC Kalpathy road km 0/00 to 2/030	Pot Holes Developed at km 0/00 to 2/030	Work on progress
17	Mezhathur Vattolikkavu Road km 0/000- 2/000	Pot Holes Developed at km 0/000-2/000	S.N . Issued
18	Mezhathur Vattolikkavu Road km 2/000- 3/100, 3/800 -4/200	Pot Holes Developed at km 2/000-3/100, 3/800 -4/200	S.N . Issued
19	Palathara Kodumunda Road km 0/000- 3/000	Pot Holes Developed at km 0/000-3/000	Estimate submitted for Revised TS
20	Palathara Kodumunda Road km 3/000- 5/000	Pot Holes Developed at km 3/000-5/000	Quotation submitted
21	Thrithala Kumbidi Road km 0/000-3/100	Pot Holes Developed at km 0/000-3/100	Amount Allotted Rs. 12.00L

LA-3093

3.

22	Thrithala Kumbidi Road km 12/000-14/720	Pot Holes Developed at km 12/000-14/720	Amount Allotted Rs. 18.00L
23	Krishnapadi Kayiliyad road at km 4/500	Retaining wall Collapsed at Km 4/500	Amount Allotted for Reconstruction Rs. 10.50L
24	Manissery Cherottur road at km 2/150 in Ottappalam Section.	Retaining wall Collapsed at Km 2/150	Amount Allotted for Reconstruction Rs. 12.33L
25	Vaniyankulam Mannannur railway station road in Ottappalam section in Shornur LAC.	Retaining wall Collapsed at Km 3/960	S.N. Issued
26	Venganoor Bridge approach	100 m washed off	Reconstructed
27	Pattambi Bridge	Hand rails washed off, Approach road collapsed; Minor defects in check slab	Rectified Amount Rs. 22.63L
28	Kalladikkode Sreekrishnapuram Road	Pot Holes Developed at km 12/000	Work completed
29	Kumaramputhur Olippuzha Road	Retaining wall Collapsed at Km 14/200	Work in progress
30	Kandankulam Erattavari Road	Pot Holes Developed at km 4/400	Work completed
31	Mannarkkad Chinnathadakam Road	Land slide - at 15 Locations from km 11/400 to 15/200	Land slide cleared and traffic restored
32	Kanjirappuzha Palakkayam Road	Retaining wall Collapsed at Km 2/200	Amount Allotted for Reconstruction Rs. 30.00L
33	Agali Jellippara Road	Land Slip at Km 4/000	Work arranged for Rs. 7.00 Lakh
34	Damage occurred on surface of various PWD roads under Palakkad Roads Division	Surface damage and pot holes	Works in Various stages

LA = 3093

44

S.No	Name of work	Type of damage	Action taken
36.	Reconstruction of damaged culvert at km 0/200 of Alathur - Maruthamthadam road	Culvert collapsed	Work completed
37.	Reconstruction of side wall at km 30/500 of Vazhakkode - Alathur road	Side wall collapsed	Agreement executed


ഒരുങ്ങുന്ന ഒന്നാമം