

പതിനാലാം കേരള നിയമസഭ
പതിനാലാം സമ്മേളനം

നക്ഷത്ര ചിഹ്നമിടാത്ത ചോദ്യം നമ്പർ: 909

30.01.2019 -ലെ മറുപടി

തിരുവമ്പാടി മണ്ഡലത്തിലെ പുഴകളുടെ തീരസംരക്ഷണം


ചോദ്യം

മറുപടി

ശ്രീ.ജോർജ് എം.തോമസ്

കെ.കൃഷ്ണൻ കുട്ടി
(ജലവിഭവ വകുപ്പുമന്ത്രി)

- | | |
|---|---|
| <p>(എ) പ്രളയത്തിൽ വലിയ നാശനഷ്ടം സംഭവിച്ച തിരുവമ്പാടി മണ്ഡലത്തിലെ പുഴകളുടെ തീരസംരക്ഷണത്തിനായി സമർപ്പിച്ച പ്രവൃത്തികളുടെ വിശദാംശം ലഭ്യമാക്കാമോ;</p> | <p>(എ) പ്രളയാനന്തര പദ്ധതികൾ ഉൾപ്പെടുത്തിയിട്ടുള്ള പ്രവൃത്തികളുടെ വിശദാംശം അനുബന്ധമായി ചേർക്കുന്നു.</p> |
| <p>(ബി) ഇവയ്ക്ക് ഭരണാനുമതി നൽകുന്നതിന് നടപടികൾ സ്വീകരിക്കാമോ?</p> | <p>(ബി) ഫണ്ടിന്റെ ലഭ്യതയനുസരിച്ചും പ്രവൃത്തിയുടെ മുൻഗണന പരിഗണിച്ചും ഭരണാനുമതി നൽകുന്നതിനുള്ള നടപടികൾ സ്വീകരിച്ചു വരുന്നു.</p> |


സെക്ഷൻ ഓഫീസർ

അനുബന്ധം

SL.N O	NAME OF WORK	AMOUNT IN (Lakhs)
1	Protecting the Left bank of Iruvanhipuzha at MukkamChonad Road in KarasseryPanchayath	60.00
2	Urgent protection to the left bank of Iruvanhipuzha and upstream side of MukkamKadavu bridge in KarasseryGramapanchayath	90.00
3	Protecting the right bank of Cherupuzha at Palakkathottil near House No.3/40 A and 3/41 in KarasseryPanchayath	30.00
4	Protecting the right bank of Chaliyar near the House of TharammalKuttoossa in KodyathurPanchayath	30.00
5	Natural Calamity 2018-Protecting the left bank of Iruvanhipuzha near Pullooramparathuruth in ThiruvambadyPanchayath	45.00
6	Protecting the right bank of Cherupuzha near House No.11/254 and 2 other houses at KarasseryPanchayath	45.00
7	Protecting the right bank of Iruvanhipuzha near the house no 19/303 at Thrikkayathil in Mukkam Municipality	25.00
8	Protecting the Left bank of Iruvanhipuzha at Verankadavu Road at Chakkingal in KodyathurPanchayath	10.00
9	Protecting the right bank of Chaliyar at ParayangadBagavathi Temple in Kodyathur Panchayath	40.00
10	Protecting the left bank of Iruvanhipuzha the u/s of Thrikkadamanna temple pump house in Karassery Panchayath	20
11	Natural Calamity 2018-Protecting the right bank of Iruvanhipuzha at Thrikkezhath Kadavuparamba in Mukkam Municipality	25.00
12	Protecting the right bank of Chalipuzha u/s of Parappatta VCB in KodencheryPanchayath	23.00
13	Protecting the right bank of Edatharapuzha upstream of Anakampoil bridge in Thiruvambady panchayath	20.00
14	Protecting the Left bank of Randampuzha at Palakkamthody Parambu in Puthuppady Panchayath	30.00
15	Protection of the Left Bank of Iruvanhipuzha downstream of Theyyathumkadavu bridge at Karattukarimbanakandi thazhe in Kodyathur Panchayth.	8.00

16	FD -Urgent side protection work of Iruthullipuzha (Mattikkunnu thodu) in Puthuppadi Panchayath Thiruvambady LA/Kozhikode District	40.00
17	FD-Urgent side protection works in between Kadungathodu Edayachalil reach at Kannappankundu Puthuppadi Pt	78.50
18	FD-Urgent protection worksto Pathippara -Kakkavayal thodu on U/S of Kakkavayal VCB cum bridge in Kakkavayal Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	25.00
19	FD-protecting sides of Pottikkai thadayanamukku thodu in Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	24.00
20	FD-Short term works-Urgent side protectionworks to Panachikkal thodu at Kakkad in Puthuppadi Pt of Thiruvambady LA Kozhikode Dt	12.00
21	FD-Side protection works to Muppathekkar puzha in Puthuppadi Pt of Thiruvambady LA Kozhikode Dt	39.00
22	FD-protecting sides of Thudarapuzha at Kannappan kundu in Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	25.00
23	FD-protecting sides of Mattikkunnu thodu in ward No.2 of Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	20.00
24	Urgent repair works to Payona VCB in Kakkavayal thodu in Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	7.00
25	Urgent repair works to Manalvayal VCB cum bridge in Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	7.00
26	Urgent protection works to Panachikkal VCB in Kakkad-Panachikkal thodu in Puthuppadi Pt of Thiruvambady LA/Kozhikode Dt	7.00

[Handwritten Signature]
50