


പതിനാലാം കേരള നിയമസഭ
പതിനഞ്ചാം സമ്മേളനം

നക്ഷത്ര ചിഹ്നമിടാത്ത
ചോദ്യം നമ്പർ:5800

02.07.2019-ലെ മറുപടി


പത്തനംതിട്ട മുനിസിപ്പാലിറ്റിക്ക് അനുവദിച്ച തുക

ചോദ്യം		മറുപടി	
ശ്രീമതി.വീണാ ജോർജ്ജ്		കെ.കൃഷ്ണൻ കുട്ടി (ജലവിഭവ വകുപ്പുമന്ത്രി)	
(എ)	പത്തനംതിട്ട മുനിസിപ്പാലിറ്റിക്ക് ഈ സർക്കാർ പൈപ്പ് മാറ്റി സ്ഥാപിക്കലിനും ജലലഭ്യത ഉറപ്പുവരുത്തുന്നതിനുമായി എത്ര തുക അനുവദിച്ചിട്ടുണ്ട്;	(എ)	പത്തനംതിട്ട മുനിസിപ്പാലിറ്റിയിൽ പൈപ്പ് മാറ്റി സ്ഥാപിക്കലിനും ജലലഭ്യത ഉറപ്പുവരുത്തുന്നതിനുമായി വിവിധ പദ്ധതികളിൽ ഉൾപ്പെടുത്തി ഈ സർക്കാർ അനുവദിച്ച തുകയുടെ വിശദാംശങ്ങളും ടി പ്രവൃത്തികളുടെ നിലവിലുള്ള സ്ഥിതിയും അനുബന്ധമായി ചേർക്കുന്നു.
(ബി)	മേൽ പറഞ്ഞ പ്രവൃത്തികളുടെ നടപടിക്രമങ്ങൾ ഏതു ഘട്ടത്തിലാണ്; വിശദമാക്കാമോ?	(ബി)	


സെക്ഷൻ ഓഫീസർ

Annexure

SL NO.	Name of works	Administrative Sanction Amount in Lakhs	Present status
1	LAC-ADS 2016-17-(Go. Rt No.681/17 WRD Tvm. Dated 9/8/2017)-Infavour of smt.Veena George MLA,Aranmula LAC,Construction of tank and ground tank for the water supply sceheme to Mannarmala in Pathjanamthitta Muncipality.	30.7	Work completed
2	KIIFB-2018.UWSS to PTA-Replacing damaged AC pipe line at Pathanamthitta Town area.	1122.69	Technical sanction estimate under scrutiny
3	STATE PLAN-2018-2019 GO(Rt)No.615.18/WRD Tvm Dated 20/08/2018		
3(a)	UWSS to PTA-Providing gallery Chamber and leading pipe at Kallarakkadavu intake pump house.	17.8	Estimate under scrutening
3(b)	Providing infiltration gallery chamber and relaying gallery pipe at Kumbazha intake pump House.	18	Estimate under scrutening
4	STATE PLAN-2016-2017 GO(Rt)No.119:2017:WRD Dated 14/02/2017		
4(a)	UWSS to PTA-Providing Chlorinator at Treatment plant.	3	Work completed
4(b)	UWSS to PTA-Installing Raw Water 150 HP VT. Pumpset at intake pump house Kallasakadavu	21.8	Work completed
4(c)	UWSS to PTA- Replacing damaged 150 mm AC pipe line with 160 mm pvc pipe from Makkamkundu to karimpinamkuzhi.	14.1	Work completed


 സെക്ഷൻ ഓഫീസർ