പതിനാലാം കേരള നിയമസഭ ഇരുപത്തി രണ്ടാം സമ്മേളനം

നക്ഷത്ര ചിഹ്നമിടാത്ത ചോദ്യം നം. 914

14-01-2021 ലെ മറുപടി

പിറവം നിയോജക മണ്ഡലത്തിൽ ജലവിവേ വകപ്പ് നടപ്പിലാക്കിയ പദ്ധതികൾ

	ചോദ്യം	മറുപടി
	ശ്രീ. അന്തപ് ജേക്കബ്	കെ. കൃഷ്ണൻകുട്ടി
		(ജലവിഭവ വകപ്പുമന്ത്രി)
(എ)	ജലവിഭവ വകപ്പിന്റെ	ഈ സർക്കാർ അധികാരത്തിൽ വന്നശേഷം
	ആഭിമുഖൃത്തിൽ പിറവം നിയോജക	നാളിതുവരെ മേജർ, മൈനർ ഇറിഗേഷൻ
	മണ്ഡലത്തിൽ വിവിധ	ഡിവിഷൻ എറണാകളം മുഖേന പിറവം
	മിഷനുകൾക്കും പദ്ധതികൾക്കും	മണ്ഡലത്തിൽ നടപ്പിലാക്കിയ പ്രവർത്തികളുടെ
	(എ) കീഴിൽ 2016 ജൂൺ മുതൽ	വിശദാംശങ്ങളുടെ പട്ടിക അനുബന്ധം 1 ആയി
	&	ഉള്ളടക്കം ചെയ്യന്നു.
	നടപ്പിലാക്കിയ പദ്ധതി	പിറവം നിയോജകമണ്ഡലത്തിൽ മുവാറ്റുപുഴ വാലി
	പ്രവർത്തനങ്ങളുടെ വിശദാംശം (ബി)) ഇറിഗേഷൻ പ്രോജക്ട്, പെരിയാർവാലി
	ലഭ്യമാക്കുമോ;	ഇറിഗേഷൻ പ്രോജക്ട് എന്നീ പദ്ധതികളിലായി
(ബി)	പ്രസ്തുത കാലയളവിൽ മൈനർ	2016–17, 17–18, 18–19, 19–20 എന്നീ സാമ്പത്തിക
	ഇറിഗേഷനും മേജർ ഇറിഗേഷനും	വർഷങ്ങളിൽ നടപ്പിലാക്കിയ പ്രവൃത്തികൾ
	കീഴിൽ നടപ്പിലാക്കിയ	സംബന്ധിച്ചുള്ള വിശദവിവരം അനുബന്ധം 2
	പദ്ധതികളുടെ വിശദാംശങ്ങൾ	ആയി ഉള്ളടക്കം ചെയ്യന്നു.
	ലഭ്യമാക്കുമോ?	കെ.ആർ.ഡബ്ല്യൂ.എസ്സ്.എ (ജലനിധി) യുടെ
		ഭാഗമായ മഴകേന്ദ്രത്തിന്റെ നേതൃത്വത്തിൽ പിറവം
		നിയോജകമണ്ഡലത്തിലെ ആമ്പല്ലർ ഗ്രാമ

പഞ്ചായത്തിൽ തെരഞ്ഞെടുക്കപ്പെട്ട 850 <u>ഗ</u>ണഭോക്താക്കളടെ **ഇ**റന്ന കിണറുകൾ മഴവെള്ളം ശേഖരിച്ച് റീചാർജ് ചെയ്യന്ന പദ്ധതി സംസ്ഥാന സർക്കാരിന്റെ വാർഷിക പദ്ധതിയിൽ ഉൾപ്പെടുത്തി നടപ്പിലാക്കി വരുന്നു. ഇതിനോടകം കുടുംബങ്ങളിൽ നടപ്പിലാക്കി. പദ്ധതി 250 ബാക്കിയുള്ളവയുടെ നിർമ്മാണ പ്രവർത്തനങ്ങൾ പുരോഗമിച്ച വരുന്നു. മഴവെള്ളം കടത്തിവിടുന്നതിലൂടെ കിണറുകളിൽ ലഭ്യമാക്കുന്നതിന് സ്ഥായിയായി ജലം സഹായകരമാകുന്നതാണ്. കൊനോത്തുപുഴയ്ക്ക് കറുകെ കൂടിയ ലോകോട്ട റെഗുലേറ്ററിന്റെ നിർമ്മാണത്തിനായി കിഫ്ബിയിൽ നിന്നം 25.76 കോടി ത്രപയുടെ ഭരണാന്ദമതി നൽകിയിട്ടുണ്ട്. പ്രസ്തത പദ്ധതി മുഖേന നടപ്പിലാക്കി ടെൻഡർ ചെയ്ത് കരാർ പ്രവർത്തികൾ ആരംഭിക്കുകയും ചെയ്ത.

സെക്ഷൻ ഓഫീസർ

P.43-71cf

			1.43-11cf	-
r- <u>-</u>			<i>h</i>	onimo / -
	<u>etai</u>	Is of works in Piravom co	onstituency	executêd
	duri	ng the period of this Go	vernment u	ndor Mi
		Division, ERNA	ZIII AAA	muel Mi
SI		DIVISION, ERNAN		
No		Name of work	T.S amount in Lakhs	Present status
		PLAN WORKS		
	201	6 -2017		
1	Piravoi	litation of L.I Scheme - Improvements to m L.I Scheme near Palachuvadu	8.00	completed
2	Rehabi Piravor	litation of L.1 Scheme -Improvements to n L.1 Scheme near Nirappukattilpady	8.00	completed
3	Mamal	litation of L.I.Schemes-Renovation works to assery L.I.Scheme canal near Vasappady in pangalam Panchayath.	15.00	completed
	201	7-18		
1	in Koc	ication of Muttumugham Cross bar othattukulam Municipality	10.00	Work not started
2	near Kı	- Rectification Works to Kakkad L1 Scheme Iryattupady in Piravom Municipality.	15.00	completed
3	RELIS Manacl	-Rehabilitation of Pazhoor LIS Near kappady in Piravom Municipality	15.00	completed
4	RELIS - Recor and at ^	- Rehabilitation of No.4 LIS Ramamangalam istruction of Main canal near HSS at Sivali Tail end Portion	10.00	completed
5	Repairs	 Rehabilitation of Kizhumuri LI Scheme - and Reconstruction of Leading Channel near hazham Padasekharam in Ramamangalam yath 	12.00	completed
	2018			
	Sreekri	ition and rejuvenation of Karikkodu shпаригат Sree Dharma Sastha Temple pond inthuruthy grama panchayat.	20.00	completed
2	Repairs retainin	of MI Structures - Repairs to culvert and g wall of sluice at Moppattuthazham	3.15	ongoing

	near Kuryattupady in Piravom Municipality.	15.00	completed
3	RELIS-Rehabilitation of Pazhoor LIS Near	15.00	completed
	Manackappady in Piravom Municipality		•
	RELIS - Rehabilitation of No.4 LIS Ramamangalam	10.00	completed
4	- Reconstruction of Main canal near HSS at Sivali		
	and at Tail end Portion		
5	RELIS - Rehabilitation of Kizhumuri LI Scheme -	12.00	completed
	Repairs and Reconstruction of Leading Channel near		
	Kunnilthazham Padasekharam in Ramamangalam		
	Panchayath		
· · · · · · · · · · · · · · · · · · ·	2018-19		
1	Renovation and rejuvenation of Karikkodu	20.00	completed
	Sreekrishnapuram Sree Dharma Sastha Temple pond	,	
	in Mulanthuruthy grama panchayat.		
2	Repairs of MI Structures - Repairs to culvert and	3.15	ongoing
	retaining wall of sluice at Moppattuthazham	_	
	Adiyakkal thodu, in Chottanikkara panchayat.		
3	Repairs of sluice in MI Structures - Maintenance of	5.38	ongoing
*	sluice no.1 in Amballoor panchayat.		
4	Repairs and Maintenance of V C B at	5.00	completed
	Neerinalthazham in Maneed Panchayath		
5	Repairs and maintenance of VCB Parasserythazham	5.00	completed
	in Maneed Panchayath.		1000-42000
6	Repairs to MI Structures- Repairs to canal sluices in	4.15	ongoing
	LI Scheme canals in Ramamangalam and Pampakuda		36
	Panchayats(No.1 LIS, No. 2 LIS, No. 3 LIS, No. 4		
	LIS Ramamangalam, Kizhumury LIS, Mamalassery		
	LIS and Pampakuda relift LIS) and vent way shutter		
	of Ooranattu chira check dam cum regulator		
	,		
7	Rennovation Works To Oozhakkottuchira in ward	41	ongoing
	no-2 of Edakkattuvayal Panchayath		

Haritha Keralam - Improvement works to Vattamattom kulam in Pampakuda panchayath and Narayani kulam in Ramamangalam panchayath.	11	ongoing
RELIS - Rectification Works to Kakkad LI Scheme main canal from ch 900-1200m in Piravom Municipality.	10	completed

! i

	2018-2019		
1			
	Rectification of Puthenchira Cross bar in Thirumarady Panchayath	4.99	On going
2	Annual Maintenance of Thottarapuncha Thodu In The Upstream Of Olippuram Sluice For The Year 2018-19.	12.88	completed
3	Annual Maintenance Of Thottara Puncha Thodu	15	completed
	From River mouth to Olippuram Sluice and	13	completed
	Maintenance of Petty and Para For The Year 2018-		
	Annual Maintenance of Amballoor-Keecheri Bund for 2018-2019	15	completed
5	Flood damage 2018- Maintenance of Mulakkulam	5	completed
	Vadakkekkara L I Scheme in Piravom L A		-
	Constituency-Desilting of leading channel to suction pit		
	Annual maintenance of Kalampoor north L I scheme for the year 2018-2019	0.7	completed
	Annual maintenance of Kakkad tailend L1 Scheme for the year 2018-2019	1.7	completed
8	Annual Maintenance of Pazhoor L I Scheme for The Year 2018-2019	3.6	completed
9	Annual Maintenance of Nechoor L I Scheme for The Year 2018-2019	4	completed
	Flood damages 2018-Urgent rectification works to Mulakkulam Vadakkekara L 1 Scheme	5	completed
	Annual Maintenance of Kalampoor South LIS for the Year 2018-19	4.5	completed
<u> </u>	Flood damage 2018- Urgent rectification works to Mulakkulam North LI Scheme.	6.5	completed
	Flood damage 2018-Urgent rectification works to Puthumanakkadavu LIS	5.1	completed
	Flood damage 2018-Urgent rectification works to Kakkad LI Scheme	5.4	completed
	Annual maintenance of Piravom LIS for the year 2018-19	6.2	completed
	Urgent rectification works at various reaches of Manakkathoombu thodu near tail end of Pazhoor LIS in Division No 23 of Piravom Municipality	15	completed
17	Urgent rectification works to the left bank of Uzhavoor thodu at the upstream of Chaliyathuchira	10	ongoing
	in Division No.3 of Piravom Municipality 2019-2020		
1	Rectification of Naolimattam checkdam in ward no.2		Work not
	of Thirumarady Panchayath in Piravom Constituency	8.00	started
2	M.I.PRIORITY-Rectification of damaged		
	VCB and leading channel at		Work not
	Valiyappadom in Thirumarady		started
	Panchayath of Piravom Constituency.	15.00	
3	Annual maintenance of Adiyakal thodu and Manchakattu chal at Chottanikara Panchayath Emakulam district for the year 2019-2020	15	completed

4	Annual Maintenance of Thottarapuncha thodu in the	10	completed
	upstream of Olippuram sluice for the year 2019-2020		
L			
5	Annual maintenance of Thottarapunchathodu from	13.2	completed
	Rivermouth to Olipuram sluice and maintenance of	13.2	completed
	Petty & Para for the year 2019-20	}	
6	Annual maintenance of Pallippuram puncha thodu		
1	and knjame in Charactitions at Pamppurant pulkna though	3	completed
	and kulams in Chottanikkara panchayat for the year		
7	2019-20.		
'	Annual Maintenance of Amballoore - Keecheri Bund	4.2	completed
 	for the year 2019-2020		•
8	Annual maintenance of Kalampoor north, Kalampoor	0.31	completed
	south and Kakkad tail end LI Schemes for the year		completed
<u></u>	2019-2020		
9	Annual maintenance of Mulakkulam North L I S for		
_	the year 2019-2020	5	completed
10	Annual maintenance of Duchamanal 1		
-	Annual maintenance of Puthumanakkadavu L I S for the year 2019-2020	5	completed
11			
**	Annual maintenance of Kakkad L I S for the year	5	completed
	2019-2020		F
12	L immunermired of McCHOOL F 1 2 Kill life Abak 1	5	completed
	2019-2020	J	completed
13	Annual maintenance of Mulakkulam Vadakkekkara L	5	
[I S for the year 2019-2020	5	completed
14	Annual maintenance of Piravom L I S for the year		
- :	2019-2020		completed
15			
1 13	Annual maintenance of Pazhoor L I S for the year	4.99	completed
1	2019-2020		
10	MIRPA-Revamping-Reconstruction of Nechoor LI	10	completed
	Scheme in Maneed Grama Panchavath	10	completed
17	MIRPA- Revamping- Rectification work of	-	
	Mamalassery LI scheme including construction of a	5	ongoing
	culvert for earthen road near ch. 4570 m.		
18	MIRPA special packageekm Improvement works	·	
	to Mamplacem, I.I. all improvement works	25	ongoing
	to Mamalassery LI scheme between ch 4100 m		
	and 4700m including raising of aqueduct near		
	<u>CD 4 (bU m </u>	VIII.	
19	Annual maintenance of LI schemes in	4	completed
	Ramamangalam and Pampakuda panchayath.	•	completed
	2020-2021		
	Construction of leading shared at V.		
1	Construction of leading channel at Kadymattam padam	12.40	Work tendered
	in Koothatukulam Municipality(2020-21)	12.40	Mork reliaeled
2	Annual maintenance of Thottarapunchathodu from	15	ongoing
4	Rivermouth to Olipurarh sluice and maintenance of		
	Perty & Para for the year 2020-21		
_	Annual Maintenance of Thottarapuncha thodu in the	10	Ongoine
3	upstream of Olippuram sluice for the year 2020-21	10	ongoing
4	Annual maintenance of Amballoore keecheri bund		
4	2020-2021	4.6	ongoing
I.	-V-V &V&L		1
	Annual Maintonance - Cln		
5	Annual Maintenance of Ramamangalam No.1 LIS & Mamalassery LIS for the year 2020-21.	5	ongoing

	Appual maintenance - CD		
6	Annual maintenance of Ramamangalam No.2 LIS,	8	ongoing
`	No.3 LIS, No.4 LIS & Kizhmuri LIS for the year 2020-21.		
_			
7	Annual Maintenance of Pampakuda Relift for the year 2020-21	5	ongoing
8	Annual maintenanace of Piravom LIS for the year 2020-21	5	ongoing
9	Annual maintenanace of Mulakkulam Vadakkekkara	5	ongoing
	LIS for the year 2020-22		
10	Annual maintenanace of Mulakkulam North LIS for	5	ongoing
	the year 2020-23		
11	Annual maintenanace of Kakkad LIS for the year	5	ongoing
	2020-24		
12	Annual maintenanace of Kakkad tail endLIS for the	5	ongoing
-	<u>year 2020-25</u>		- Boz.B
13	Annual maintenanace of Nechoor LIS for the year	5	ongoing
-	2020-26	-	0b
14	Annual maintenanace of Kalampoor North &	0.25	ongoing
	Kalampoor South LIS for the year 2020-27	•	01.60116
15	Annual maintenanace of Puthumanakkadavu LIS for	5	ongoing
	the year 2020-28	Ŭ	OHEOTHE
16	Annual maintenanace of Pazhoor LIS for the year	5	opaoina
	2020-29	J	ongoing
	Improvements to the Main canal of Nechoor LI	15	selection notice
17	Scheme at tail end portion from CH.2970 m to	13	i i
	tailend (After Aqueduct portion)		issued
	Emergency work- Rectification works in the tail end	2.8	
18	portion of Elayapadam branch canal of No.2 LIS	2.0	completed
	Ramamangalam.		
	SDRF -WORKS		
	2018-2019		
1	SDRF - Cleaning and Desilting of		
	Uzhavoor thodu U/S of Muttumugham		
	VCB in Koothattukulam Municipality of		
	Piravom Constituency		Work
		4.99	Completed
2	SDRF - Cleaning and Desilting of Pynkutty		
	Thodu from Pynkutty bridge in Elanji		
	Panchayath of Piravom Constituency		Work
		2.49	Completed
3	SDRF - Rectification of Palathanam chira		Compiceed
	in Koothattukulam Municipality of		NAVA AL.
	Piravom Constituency		Work
		4.90	Completed
~*	SDRF-Flood protection-Bund- Rectification		
	of damaged portion of paddy field side		
	near Keezhichira in Thirumarady		
	panchayath of Piravom Costituency		Work
		4.93	Completed
			Javinpiceca

ţ

			•
5	SDRF-Urgent rectification of damaged		
	side wall of Thirumarady Vadakkum		•
	padom thodu D/s of Puthen chira		
	Crossbar in Thirumarady Panchyath of		Work
	Piravom Constituency	4.97	1
6	SDRF - Rectification works to Pinmattom	4.97	completed
"			
	-Chadayan kavu leading channel of		
	Muttumugham cross bar of		
	Koothattukulam Municipality in Piravom		Work
	Constituency	4.90	completed
7	SDRFI- Cleaning and Desilting of		
ĺ	Uzhavoor thodu D/S of Muttumugham		
	VCB in Koothattukulam Municipality of		Work
	Piravom Constituency	4.99	Completed
8	SDRF - Rectification of Karingamattom	7.33	Completed
	Cross Bar and repair of damaged leading		
	channel in Koothattukulam Municipality		l
	of Piravom Constituency		Work
		4.50	Completed
9	SDRF-Rectification of damaged outer	-	
	bund of Vakamattom Kannangadi paddy		
	field -Mannathoor Pallithazham thodu in		
	Thirumarady Panchayath of Piravom		Work
	Constituency	4.97	Completed
10	SDRF - Rectification works to		00111010000
	Karappadavu leading channel of Raman		
	chira cross bar of Koothattukulam		1444.
	Municipality in Piravom Constituency	4.50	Work
11	SDRF - Cleaning and Desilting of	4.50	Completed
	Vettivody Thody in Florid Denshaustic (
	Vettiyody Thodu in Elanji Panchayath of		Work
3.3	Piravom Constituency	4.90	Completed
12	SDRF - Cleaning and Desilting of Various		
	reaches of Uzhavoor thodu(Mangalathu		
	thazham bhagom) in Koothattukulam		Work
	Municipality of Piravom Constituency	4.99	Completed
13	SDRF-Urgent rectification of damaged		
	side wall of Edayar -Kadavum pattu		
į	thodu near Ambalakkadavu in		
	Koothattukulam Municipality of Piravom		Work
	Constituency	2.45	1
14	SDRF - Rectification of Chackyal V.C.B in	4.43	completed
*	Elanji Panchayath of Piravom		
	Constituency ,	5 45	Work
		2.45	Completed
15	SDRF - Cleaning and Desilting of Various		
	Thodu in Thirumarady Panchayath of		Work
	Piravom Constituency	4.90	completed
16	SDRF - Rectification of Peruvely V.C.B in		
	Elanji Panchayath of Piravom		Work not
	Constituency	4.90	started
		4,30	praired

į

17	COOC David Co.		
P 1/	SDRF - Rectification of Chirappalamattom		
	V.C.B and damaged leading channel of		
1	Palamattom V.C.B in Koothattukulam		
Ţ	Municipality of Piravom Constituency		Work
İ		4.90	1
18	SDRF - Rectification works to Kothodam	4.50	completed
~~	leading channel of Roman chira cases have		
	leading channel of Raman chira cross bar		
	of Koothattukulam Municipality in		Work
	Piravom Constituency	4.20	Completed
19	SDRF - Rectification of various Vented		
	Cross bars in Thrumarady Panchayath of		75% of work
	Piravom Constituency	4.99	completed
20	SDRF work-Cleaning of Ettupara thodu at		··
	Mampuzha in Amballoore Panchayath.	1.2	completed
21	SDRF work- Cleaning of Ambazhavelil thodu near		
~ -	Millunkal Jn. in Amballoore panchayath	1.2	completed
22	SDDE work Classics of Estimated		
44	SDRF work- Cleaning of Ettupara thodu at	1.2	completed
23	Mannarveli in Amballoore Panchayath.		
23	SDRF work- Cleaning of Ambazhavelil thodu near	1.2	completed
	Kanjiramattam Railway station in Amballoore		
<u> </u>	Panchayath.		
24	SDRF work- Cleaning of Pallippuram punch athodu	1.2	completed
	in Chottankkara panchayath.		
25	SDRF work- Cleaning of Adiyakkal branch thodu	1.2	completed
	from Kizhkkavu road in Chottanikkara Panchayath.		· i
26	SDRF work-Cleaning of Branch thodu near	1.2	completed
1	Thalakkode LI scheme in Chottanikkara Panchayath.		
	:		
27	SDRF work-Cleaning of Kurumbathu thazham -	1.2	completed
	Kappil thazham thodu in Ayyakunam Padasekharam		·
	in Edakkattuvaval Panchavath		
28	SDRF - Rectification of damaged canal near	1.5	completed
	Kudiyirikkapady of Piravom L I Scheme in Piravom	2.2	
	Municipality.		
29	SDRF Work - Rectification of damaged canal near	1.5	completed
	tail end of piravom L1 scheme	₩ 7₩	
30	SDRF work-2018-Rectification of damaged canal	1.5	completed
	near tail end of kalamboor LI scheme	# · U	**************************************
31	SDRF work-Desilting of Kuthiyathodu in Amballoor	15	completed
	panchayath	10	Completed
32	SDRF work- Desiliting of Chalithazham thodu in	15	completed
	Mulanthuruthy Panchayath Reach-1	13	compaced
33	SDRF work-Cleaning of Karikode canal tail end to	1.1	completed
""	Thuruthykkara main branch thodu in Mulanthuruthy	7+7	compieted
1	Panchayath]
34	SDRF work- Desilting of Koomullithazam thodu in	3	completed
	Mulanthuruthy Panchayath.	၁	completed
35		* P	e a manufactural
, ,,	SDRF work- Desiliting of Chalithazham thodu in	1.5	completed
36	Mulanthuruthy Panchayath Reach-2	* 4	
30	SDRF work-Cleaning of Thuruthikkara to Panar	1.1	completed
Ь	thodu branch in Mulanthuruthy Panchayath.		<u>, l </u>

3	in Mulanthuruthy Panchayath	1.5	completed
3	8 SDRF - Repairs for leading channels to		
	Pampooripadam from No.1 LIS Ramamangalam	1.5	completed
<u></u>	IVIGUCII Canal.		
3	9 SDRF work- Desiliting of Pulikkamaly -Amachottil		
	thodu in Mulanthuruthy Panchayath	1.5	completed
4(SDRF work -Desilting of Paingali thodu in		
	Mulanthuruthy Panchayath	1.5	completed
4	SDPF work Death		
•	" Taran work Desirate Of Pallakkara (Podin in	1.5	completed
42	Amballoor Panchayath		completed
74		1.5	com-les-d
4.7		1	completed
43	DURF WORK- Desiliting of Paingarapilly Verilland		
	INDUA DI MUNICIPALINI DI PARCHAMATA	1.5	completed
44	SURF work - Desilting of Kanayannon the de		
	Kanayannoor temple in Chottanikkara Panchayath	3.1	completed
	IXEGLII Z.		
45	SDRF works- Kizhmuri LIS -Rectification works to		
	tail end portion of loading about 100 Rectification works to	3	completed
	tail end portion of leading channel of Ullelipadam		
	from Kizhmuri LP school and repair of upstream reaches near CH 400m		
46			
70	The worn a Metrillealing Morks to Mone 2-1	1.5	completed
47	Totalicii Canal Of No. 2 LTS Damamanala	1.0	completed
4/	SURF - Repairs and restoration of Clausers	1.5	
	Provider Carlai VI IVO. II I. IX Ramamagalam	1.5	completed
40	MARINGUISTING HS and after colors		[
48	DENT - RECUITCATION OF Main canal none Chitago		
	Principally LIS Dear Kithmury echool in all at	1.5	completed
	restoration of leading channel through the side of		
			Ĭ
49	SDRF work - Rectification of damaged canal near		
	Viyatnam colony of Piravom LI Scheme	1.5	completed
50	SDRE work Postification		
-	SDRF work - Rectification work at left bank of main	1.5	completed
	readure of Comattuchies chook damed	2.0	completed
1	A.MARYSINIA DARRICA DARRA DA LA CARRA DE CARRA DEL CARRA DE LA CA		1
-	SDRF - Rectification work at left bank of main	3	
4	reduing Channel of Domattuchica chack domain out	J	completed
			}
2	SUKE Work- Desiliting of thoda in Kurneyland	4.0	
	Pagasekiigidii ili Amnalioora Danchaasak	1.2	completed
ر د ا	SURF WORK - Desilting of thody near Thomas it		
	CD III Muidhillillillilli Panchauath	1.5	completed
4	SDRF - Repairs No: 1 LIS Ramamangalam branch		
_	canal near CH 300m	4	completed
5 (SDRF - Renairs to left side land		
ļ	SDRF - Repairs to left side leading channel from	2.3	completed
ļ.	Ramamangalam market of No.1 LI Scheme		- will protect
	<u>yamanangalam.</u>		1
	DRF - Desiltation of Verapilly Puncha	15	Acres les - 3
Ir	duaseknaram 0 - 2000 m ch (unstream of access	1.J	completed
			[
' S	DRF works - No.1 LIS Ramamangalam leading		
c	The valuation of the property	7.1	completed
	ranch canal.		ī

58	SDRF work - Desilting of Millunkal thodu in		
	Kanjiramattom in Amballoor Panchayath	15	completed
59	SDRF. Rectification work as \$1.00 Miles		
75	SDRF- Rectification work to No.2 L1 scheme	8	completed
	Ramamangalam main canal near CH		•
60	2170.2200.2350.2380.2410		
OU	SDRF work- Desilting of Panar thodu in	15	completed
	Mulanthuruthy panchayath		completed
61	SDRF-Rectification of main canal in Nechoor L I	15	completed
	Scheme in Maneed Panchayath	10	completed
62	SDRF-Rectfication works of main canal between Ch.	15	
	1250m to 1350m and 3100m to 3280m of Pazhoor L	15	completed
	1 Scheme in Piravom Municipality.		
63	SDRF-Rectification works of main canal between		
	Ch2400-2550m and between 2800-2900m of	15	completed
	Mulakkulam North L I Scheme in Piravom		
ļ	Municipality		
64	SDPE Postfortion of County is		
5	SDRF-Rectfication of C canal at tail end portion of	15	completed
65	Piravom L I Scheme in Piravom Municipality.		
	SDRF-Urgent rectification works to Piravom L I S	15	completed
	main canal from Ch: 2600m-2880m in Piravom		
	Municipality		
66	SDRF - Rectification of branch canal near	15	completed
þ	malsyacolony of Kalamboor south L I Scheme in	10	Completed
	Pirayom Municipality.		
67	SDRF work- Desiliting of thodu near Karikkode	1.5	
1	temple in Mulanthuruthy panchayath.	1.5	completed
68	SDRF work- Desilting of Kanayannoor thodu near		
	PVIP canal in Chottanikkara panchayath Reach I	3	completed
69	SDRF work - Desilting of Pallithazham to		
ا د	Kolanchorikodorn abada 10 Kolanchorikodorn abada 10 Kolanchorikodorna abada 10 Kolanchorikodorna 10 Kolanchorikodo	3.3	completed
Ľ	Kolancherikadavu thodu in Mulanthuruthy		
70	panchayath SDDD		
/U	SDRF work - Rectification of Sluice and side walls	3	completed
Įŝ.	at Koonampalathazham in Mulanthuruthy		,
	Panchayath		
71	SDRF work - Rectification of sluice and desilting of	5	completed
ļu	ipstream and downstream thodu at Aniilivelithazham	J	completed.
	n Amballoor panchavath.		
72 9	SDRF- Rectification of sluice and desilting of	5	completed
Ju	ipstream and downstream thodu at	3	completed
	Vellarimalathazham in Amballoor panchayath		
73 5	DRF-Rectification of main canal between ch,2450-	10	
12	2730 of KakkadLI Scheme in Piravom Municipality	15	completed
	of tannada Scheme in Filavoni Municipality		
74 5	SDRF-Rectification of main canal between ch1155-		
. ,]	410 m of Aulaklaniam Valanta Derween chilish-	15	completed
	410 m ofMulakkulam Vadakkekkara LI Scheme in		
75 S	Piravom Municipality		
- 1-	DRF work - Rectification of sluice at	5	completed
1.	yalathupadam and desiliting of upstream and		1
	OWIStream thodu in Amballore panchavath		
/6 S	DRF work- Rectification of sluice and desilting of	5	completed
ļu	pstream and downstream thodu at Pulikkamali in	U	- Compacted
0	Aulanthuruthy Panchayath		1
77 S	DRF-Rectification work of Poothrikka branch	15	completed.
lc.	anal of Puthmanakkadayu L I Scheme in Maneed	13	completed
p	anchayath		1
			1

78	TO THE PROPERTY OF THE PROPERT	10	completed
70	<u> BCHEIRE CANAL NEAR COH 400 1000 1200 6, 2200</u>		completed
/9	SURF - Rectification works for west branch sens!	1.5	completed
	(Omaking from CH 70m of main canal) near CH	1.5	completed
-	DVIII VI IVOLIV LIS Ramamangalam		
80	SDRF works- Rectification of damaged outer hund	3	
	of Main canal near CH 400m - of No IV I IS	,	completed
<u> </u>	Ramamangalam.		
81	SDRF- Rectification work to Mamalassery LI	15	
	scheme - maincanal near CH 3500 3800 4100 &	15	completed
	15100 m		j
82	SDRF works -Repairs and restoration for piers of		
	Aqueduct near CH 400m of No.111 LIS	٥	completed
	Kamamangalam		
83	SDRF work -Rectification of Sluice and desiliting of		
	upstream and downstream thodu of Navillithesham	6.5	completed
	<u>at Culluatioof Danchavath</u>		
84	SDRF works -Repairs and restoration for pions of	7	
ı	Address of Maria is a second capal of Maria is a	6	completed
	i dilalianikalam		
85 I	SDRF Urgent rectification works to main and it		
ľ	racious of occient from the laken to other as	7.1	
[/	Mannarathuruth in Piravom Municipality (
80	DUKE Urgent rectification works to C const. of D:	1.0	work tendered
J,	of Scheme near chanderiopady from ch: 476m to 517	1.5	
87	DRF Urgent rectification works to C canal of Piravom	11.3	work tendered
רו	- Octobre real Catholitikkanady trong chie 17m to 217 1	11.5	
- 4	in t mayour intuincipanty		work tendered
יוו	Major Irrigation		MOLK (GLIGGLEG

L.A Qn.No.914

Major Irrigation

ĺ		Welet Wilsania		
	2016-17	NON-PLAN WORK	(S	
1	Protect	ing the Left bank of Muvattupuzha River near Fishermen colony in Division No 1 of Piravom Muncipality.REACH I.	1500000	COMPLETED
	2018-19			
2	I TATOLAGICE	Damages 2018 Protecting the Left bank of apuzha River in ward NO 9 of Ramamanglam yath-Erumbil bhagam- upstream of Manackal kadayu	2500000	WORK NOT STARTE
	2019-20			
3	in I	images 2018-Protection works to the upstream boor Bridge right bank of Muvattupuzha River Division No 20 of Piravom Muncipality-	2500000	35% COMPLETED
4	: Flood Muvattupu	Damages -2018 Protecting the Left bank of zha River in Sy.No.601/54 in Division No 1 of Piravom Muncipality.	2500000	WORK TENDERED
	2018-19	PLAN WORKS		
	2018-19			

-				
1		ecting the Left bank of Muvattupuzha River near hu Lift Irrigation Scheme in Ward No.2 of Piravon Muncipality.(50m)	1 1500000	90%COMPLETED
2	: Pro	tecting the left bank of Muvattupuzha river near ad fisherman colony in division No 1 of piravom Muncipality -REACH II	1000000	WORK NOT STARTED
		MISCELLANEOUS WORKS & DEPOSIT WOR	RKS EXCEPT MLA, MU	JZIRIS
1	SDRF-	Irrigation Division Ernakulam -Repairs to the left Muvattupuzha river in Thottabhagam,, opposite tutheeram park in Division No. 19 of Piravom Muncipality	T	COMPLETED
2	h ikin ogk	rrigation Sub division Piravom -Repairs to the of Muvattupuzha river ear Madakkil Sree ali Temple in ward No. 5 of Maneedu Panchayath	15,00,000	COMPLETED
3	RO OK TIK	rigation Division Ernakulam-Rectification works ht bank of Muvattupuzha river in ward No. 3 of Panchayath downstream of Thondikadavu	20,00,000	COMPLETED
				i .

nwayand andlowed

1.25-37cT

·		Bron	Donlaro
SI No.	Name of work and scheme	Estimate Amount (Rs.in Lakhs)	Status of wor
	2016-17		
<u> </u>	MVIP		
1	MVIP- LBMC engaging shutter operator cross bund other connected works for water distribution through LBMC 25,600M to 37110M,Mulakkulam branch,Piravom branch and their distributories for the year 2016-2017	3.00	Completed
2	MVIP- LBMC- Urgent rectification works to main canal from Ch. 25700m to 26500m for the year 2016-17	15.00	Completed
3	MVIP- LBMC- Urgent rectification works to main canal from Ch. 26500 to 27300m for the year 2016-17	15.00	Completed
	MVIP- LBMC- Urgent rectification works to main canal from Ch. 27300m to 28100m for the year 2016-17including maintenance	15.00	Completed
5	MVIP- LBMC- Urgent rectification works to main canal from Ch. 28100m to 28900m for the year 2016-17	15.00	Completed
	MVIP-LBMC Rectification work of canal at outlet of Kizhakombu tunnel and protecting the sides near Ch. 32100m to 32400.	15.00	Work pending due to water logging
	MVIP- Urgent rectification works and protection works to Piravom branch canal near ch.2900m.	11.00	Completed
	MVIP- Urgent rectification works to Piravom branch canal near ch.6300m.	4.00	Completed
	MVIP- Rectification works to Mulakkulam branch canal between Ch; 650m and 720m, 1700m and 1710m and 2600m and 3700m.	10.00	Completed
	MVIP- Urgent special maintenance to South kakkad distributory from Ch.20m to 2700m	3.00	Completed
	MVIP- Urgent special maintenance to South kakkad distributory from Ch.2710m to 5812m	3.00	Completed
	MVIP- Urgent special maintenance to South kakkad distributory from Ch.5984m to 8900m	3.00	Completed
	MVIP- Urgent special maintenance to South kakkad distributory from Ch.8915m to 11340m	3.00	Completed
1	MVIP- Urgent rectification works to South Kakkad Distributory in Detween ch.3000m to 3500m.	15.00	Completed
15	MVIP- Rectification of Koothattukulam Distributory at ch. 100m to 2000m	10.00	Completed .
	PVIP		•
16 (PVIP-Urgent special maintenance between ch:2.3km to 3km of Nechoor MD	2.00	Work completed
Į.	PVIP-Annual maintenance- Clearing blockage and slipped earth during water distribution in Kanjiramattom MD . Edakkattuvayal MD, Thiruvankulam MD and its distributories	1.50	
30 1	VIP- Urgent special maintenance between ch:0/000 to tail end of Ambalton M.D.		Work completed
10			Work completed
20 F	W.LP- Urgent special maintenance between ch: 5 km to tell end of Kanjiramattam M.D. W.LP- Urgent special maintenance between ch:6/000 km to tell end of Edakkattuväyal 4.0.	3.50 4.00	Work completed
21	V.L.P- Urgent special maintenance between ch:3.5 to 5 km of Edakkattuvayal MD	4 00	Work completed
	2017-18 MVIP	44	Work completed
1 P	AVIP -LBMC Engaging labour to water distribution works hrough LBMC 25,600m to37110m, Mulakkulam branch, iravom branch onakkur distributory, south kakkad listributory, kuthattukulam distributory for the year 2017-8	3.00	Completed

1	MVIP -LBMC Engaging labour to water distribution works through LBMC 25,600m to 37110m, Mulakkulam branch, Piravom branch onakkur distributory, south kakkad distributory, kuthattukulam distributory for the year 2017-18	3.00	Completed
2	MVIP-LBMC Annual maintance from ch.25664m to 37100m for the year 2017-2018	5.00	Completed
3	MVIP - Annual maintenance to Piravom Branch Canal from Ch. 0 m to 4150m	3.00	Completed
4	MVIP - Special Maintenance to Koothattukulam distributory after from Ch. 3915 m to 7975m	3.00	Completed

	\		
5	MVIP Annual Maintenance works to south Kakkad distributory from Ch. 20 m to 4000m	3.00	Completed
6	MVIP Annual Maintenance works to south Kakkad distributory from Ch.4000 m to 7250m for 2017-2018	3.50	Completed
7	MVIP Annual Maintenance works to south Kakkad distributory from Ch.7250 m to 11340m for 2017-2018	3.50	Completed
8	MVIP - Annual Maintenance to Koothattukulam distributory	3.00	Completed
···	from Ch. 0 m to 3725m for 2017-2018 MVIP - Special Maintenance to Koothattukulam distributory		`
9	lift sump, leading channel and pump house. MVIP - Annual Maintenance to Onakkoor distributory from	2.50	Completed
10	Ch. 0 m to 5200m for 2017-2018	4.00	Completed
11	MVIP - Water distribution for Koothattukulam Distributory LIS - Engaging skilled operators and maintenance of its sumps	2.50	Completed
12	MVIP Urgent Rectification works for Prevention of leakage to south Kakkad distributory from Ch. 5700 m to ch 5800	3.00	Completed
13	MVIP Urgent Rectification works for Prevention of leakage to south Kakkad distributory from ch 2050 m to Ch. 2150 m	4.00	Completed
14	MVIP Urgent Rectification works for Prevention of heavy leakage to south Kakkad distributory from Ch. 7900 m to ch 8200 m	15.00	Completed
15	MVIP urgent rectification works to south Kakkad distributory from Ch. 3350 m to ch 3400 m	3.00	Completed
16	MVIP - Rectification works to Koothattukulam distributory from Ch. 1200 m to 2370 m	6.00	Completed
	' İ PVIP		
17	PVIP-Annual maintenance between ch:9 km to 11 km of Kolenchery Branch Canal:	2.94	Work completed
18	PVIP-Annual Maintenance to Thiruvankulam MD 6-8km	2.45	Work completed
19	PVIP-Annual Maintenance to Nechoor MD 2.5 -tailend & Nechoor F.C	1.94	Work completed
20	PVIP-Annual Maintenance between ch 0 to 2.5 km of Kanjiramattom MD	2.94	Work completed
21	PVIP-Annual Maintenance to Thiruvankulam MD 2-4km	2.94	Work completed
22	PVIP-Annual Maintenance to Amballoor MD 0-3 km	2.94	Work completed
23	PVIP-Annual Maintenance to Thalakkode M.D 0 to 2.98km & Karikkode 0-2,40km	2.45	Work completed
24	PVIP-Annual Maintenance-Clearing blockages in culvert, cut and cover etc. in kolenchery branch canal from ch:4.6km and its distributories including Kanjiramattom MD, Edakkattuvayal MD, Thiruvankulam MD and its distributories.	1.96	Work completed
25	PVIP-Annual Maintenance between ch 2.5 km to 5.00 km of Kanjiramattom MD	2.95	Work completed
26	PVIP-Annual Maintenance to Edakkattuvayal MD 7-10KM	2.94	Work completed
27	PVIP-Rectification works between ch:0km to 1km of Edakkattuvayal MD	5.50	Work completed
28	PVIP-Providing lining in 11th km of Kolenchery branch canal to prevent leakage	10.49	Work completed
29	PVIP -Rectification works at the slipped portion of Thiruvamkulam MD near ch:7km-balance work	6.00	Work completed
-	2018-19 MVIP		
1	MVIP LBMC Annual maintenance from ch.34600m to 37100 for the year 2018-19	2.00	Completed
2	MVIP-Engaging labours for removing floating materials and other obstruction during water distribution of LBMC Its branches and distributories from Ch:25664m to Ch:37100m for the year 2018-19	2.00	Completed
3	MVIP- Rectification works to LBMC from Ch:26500m to Ch:26900m for the year 2018-19	2.00	Completed

4	MVIP- Rectification works to LBMC from Ch:28100m to Ch:28900m for the year 2018-19	12.00	Completed
5	MVIP- Rectification works to LBMC from Ch:35340m to Ch:35600m for the year 2018-19	10.00	Completed
6	MVIP- Providing and Fixing Sign Boards and Warning Boards at various chainages for LBMC from Ch.25664m to Ch.37100 m for the year 2018-19	5.00	Completed
7	MVIP- LBMC urgent rectification works to leading drain near ch. 32600m of main canal	15.00	Completed
8	MVIP-Rectification works to Piravom branch canal at Ch: 3500m to 3600m for the year 2018-19	5.00	Completed
9	MVIP-Rectification works to Piravom branch canal at Ch:3800m to 4100m for the year 2018-19	12.00	Completed
10	MVIP-Rectification works to Mulakkulam branch canal from Ch:1500m to 2400m for the year 2018-19	6.00	Completed
11	MVIP-Prevention of leakage to South Kakkad distributory from Ch:3850m to 3950m for the year 2018-19	4.00	Completed
12	MVIP-Prevention of leakage to South Kakkad distributory from Ch:4400m to 4450m for the year 2018-19	4.00	Completed
13	MVIP-Prevention of leakage to South Kakkad distributory from Ch:5050m to 5200m for the year 2018-19	4.00	Completed
14	MVIP-Prevention of leakage to South Kakkad distributory from Ch:5950m to Ch:6200m for the year 2018-19	4.00	Completed
15	MVIP-Prevention of leakage to South Kakkad distributory from Ch:10100m to 10160m for the year 2018-19	4.00	Completed
16	MVIP-Side protection works to Onakkoor distributory near Ch:80m & 800m for the year 2018-19	4.00	Completed
	PVIP		
1	PVIP-Natural Calamity -Rain damages-Temporary rectification works to Kanjiramattom MD at ch:4.00 km	1.00	Work completed
2	PVIP- Annual Maintenance Clearing blockage in culvert cut and cover etc in Kolenchery branch canal from ch:4.60 km and its distributories, Kajiramattom MD, Edakkattuvayal MD, Thiruvnakulam MD amd its distributories 2018-19	2.50	
3	PVIP-Natural Calamity -Rain damages- Rectification works to Nechoor MD near ch:5.10 km	2.95	Work completed Work completed
4	PVIP-Rectification works near ch: 7 km of Edakkattuvayal MD	5.92	
5	PVIP-Natural calamity-Rain damages-Providing side protection	3.82	Work completed
<u> </u>	works to kolenchery branch canal at ch: 12.6 km	14.15	Work completed
6	PVIP-Protection works to Kolenchery Branch canal near ch:14.00km and rectification works to damages surplus escape	20.25	Work completed
•	2019-20		
	MVIP MVIP		
1	MVIP Engaging Labour for removing floating materials and other obstructions during water distributions of LBMC and branches and it's distributories from ch: 25624m to 37100m for the year 2019-20	5.00	Work ongoing
2	MVIP LBMC-Errection of name boards,warning boards and Kilometer stones from ch:25624m to Ch:37100m for the 2019-20	5.00	Work tendered several times .No contractors responded. To be retendered
3	MVIP LBMC-Annual maintanance from Ch:25624m to Ch:27940m and Ch:30700m to Ch:37100m for the year 2019-20	5.00	Completed
4	MVIP-LBMC Urgent rectification works to main canal from Ch.25624m to Ch.26065m 1	15.00	Ongoing
5	MVIP-LBMC Urgent rectification works to main canal from Ch.29240 m to 29440.m inluding rectification works to the topof aqueducts from Ch. 28640.m to 29240.m and from Ch.29440.m to 30240.m		Work tendered. Agreement not executed
6	MVIP-Mulakkulam Branch Carlai- Providing name boards from ch: 0 m to 6770 m. for the year 2019-20	1.00	Work started
	ì		

_	MVIP-Annual maintanance to Mulakkulam branch canal from Ch:		
7	Om to Ch:6770m for the year 2019-20	2.50	Completed
8	MVIP South Kakkad Distributory Rectification works and retaining wall between Ch:1000m to Ch.1200m	5.50	Completed
. 9	MVIP South Kakkad Distributory Rectification works between Ch:6200m to Ch.6300m.	4.00	Completed
10	MVIP South Kakkad Distributory Rectification works between Ch:6700m to Ch:7000m.	4.00	Completed
11	MVIP South Kakkad Distributory Rectification works between Ch:100m to Ch.300m.	5.00	Ongoing
12	MVIP-Elanji distributory (Urgent rectification works Flume and transition Ch:475m to Ch:690m	15.00	Ongoing
13	MVIP Special maintenance to Koothattukulam distributory down stream of lift Irrigation for the year 2019-20	2.00	Completed
·	I PVIP		
1	PVIP-Flood damages 2018-Thonnalloor M D-Removal of slipped earth and making the canal water through	2.00	Work completed
2	PVIP-Annual maintenance to Thiruvankulam MD between ch: 2.00 km to 4.00 km	3.00	
3	PVIP- Annual maintenance between ch:5.00 km to 6.00 km of Edackkattuvayal M D	2.05	Work completed
4	PVIP - Annual maintenance between ch:6km to 10.20 km of Edackkattuvayal M D	5.00	Work completed
5	PVIP-Annual maintenance to Thiruvankulam M D between ch: 4.00 km to 6.00 km	3.50	Work completed
6	PVIP- Annual maintenance to Nechoor M D between ch: 2.5 km to tailend and Nechoor FC	2.25	Work completed
7	PVIP -Annual maintenance to Kolenchery branch canal 13.00km to 15.00km	4.20	Work completed
8	PVIP- Annual maintenance between ch:0 km to 3 km of	3.20	Work completed
9	PVIP- Annual maintenance between ch: 11.00km to 13.00km of kolenchery branch canal and Nechoor M D ch:0 km to 2.5 Km	3.50	Work completed
10	PVIP- Annual maintenance to Thiruvankulam M D between ch: 6.00km to 8.00 km and Thalakode MD between ch:0 km to 2.98 km	3.70	Work completed
11	PVIP- Annual maintenance to Kalamboor M D 0 km to 2.5 km	1.75	Work completed
12	PVIP- Annual maintenance to Thonnallor MD between ch: 0m to 7.55 km	4.00	Work completed
13	PVIP- Annual maintenance to Kanjiramattom M D between ch:5.00 km to 9.00 km	4.00	
14	PVIP- Annual maintenance to Amballoor M D between ch: 0 km to 3.00km	3.00	Work completed Work completed
15	PVIP- Annual maintenance to Thuruthikara M D between ch 0 km to 3.00km	2.50	
16	PVIP- Annual maintenance to karikode M D between ch: 0 km to 2.4 km	2.00	Work completed
17	PVIP- Clearing blockages in culvert cut and cover etc in Kolenchery branch canal from ch: 4.6 km and its distributories including kanjiramattom M D, Edackkattuvayal M D, Thiruvankulam M D and its distributories	2.00	Work completed
18	PVIP- Annual maintenance between ch:0 km to 3.5 km of Edackkattuvayal M D	4.00	Work completed Work completed
19	PVIP- Annual maintenance to Edakkattuvayal M D Between ch:4 km to 5 km	2.00	
	PVIP- Annual maintenance to Kanjiramattom M D between		Work completed

CADA WORKS (MVIP)2018-2019

			
1	MVIP South Kakkad Distributory Kalikulam Padashekharam - construction of leading channel		
	MVIP South Kakkad Distributors Kaliluday D.	9.44	Completed
2	MVIP South Kakkad Distributory Kalikulam Padashekharam - construction of draih.	2.25	Completed
3	MVIP CADA Kakkad Distributory Kalikulam Padashekharam		
		3.02	Completed
4	MVIP Onakkoor Distributory Chathanilam Padsekaram -		
	construction of leading channel	11.13	Completed
5	MVIP Onakkoor Distributory Chathanilam Padsekaram -		Completed
	construction of dialul	2.64	Completed
6	MVIP Onakkoor Distributory Chathanilam Padsekaram -	2.07	Completed
	construction of System Correction	2.49	
	AIBP WORKS	2.49	Completed
	MVIP- Constructing PBC from 4150m to 6604m including		
1	CD works (balance work)	85.67	
	MV/P construction Color and the time	03.07	to be arranged
	MVIP constructing Edayar distributory from ch.0m to 4215m		Work
2	4213111	1822.73	Terminated with risk and
			cost. Balance work in
3	MVIP Elanji distributory from ch. 0m to 3415m (Balance.		progress
3	work) (Balance	376.39	
			Completed
	MVIP Constructing of Koothattukulam distributory LI Scheme(Electrical)		
4	c)MVIP-Koothattukulam LIS -Electrification of	23.28	Completed
1	Pumphouse Pumphouse		Completed
5	MVIP Constructing of Koothattukulam distributory LI		
	Scheme - Electrfication of pump house, SITC of 200KVA Transformer etc - Balance work.	20.36479	Completed
	MA CINO MODICA]
	MLA FUND WORKS		
4			
ļ			Work
1	MLA Fund Improvements to canal bund road in South	177	Work ongoing
1	Kakkad distributory near ch. 4950m in Pirayom	17.7	1 1
1	Makkad distributory near ch. 4950m in Piravom Municipality.	17.7	ongoing
	Municipality. Protection wall improvements to canal bund mad of	17.7	ongoing Nearing
2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuyely in	17.7	ongoing Nearing
	Makkad distributory near ch. 4950m in Piravom Municipality.		ongoing Nearing completion
	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS		ongoing Nearing
	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP		ongoing Nearing completion
2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth	19.6	ongoing Nearing completion Completed
	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m		ongoing Nearing completion Completed
2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth	19.6	ongoing Nearing completion Completed Work completed.
2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages	19.6	ongoing Nearing completion Completed Work completed. Work
1 2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Pirayom branch canal- Removel of slipped	1.5	ongoing Nearing completion Completed Work completed. Work completed.
2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages	19.6	ongoing Nearing completion Completed Work completed. Work completed. Work
1 2 3	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages	19.6 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed.
1 2	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF-WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification	1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Work
1 2 3	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m	19.6 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed.
1 2 3	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth	1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Work
2 1 2 3 4	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between	19.6 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Work completed. Work completed. Work
2 1 2 3 4	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.3100to 1150.m	1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Completed. Completed.
2 1 2 3 4 5	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to	19.6 1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Work completed. Work completed.
2 1 2 3 4	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between	1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed.
2 1 2 3 4 5	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m	19.6 1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Work completed. Work completed.
2 1 2 3 4 5	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification	19.6 1.5 1.5 1.5 1.5 20	ongoing Nearing completion Completed Work completed.
2 1 2 3 4 5	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and	19.6 1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed.
2 1 2 3 4 5	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at Ch. 1100m and 3210m	19.6 1.5 1.5 1.5 1.5 20	ongoing Nearing completion Completed Work completed. Work completed. Work completed. Work completed. Work completed. Work completed.
2 1 2 3 4 5 6	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at ch. 1100m and 3210m SDRF-MVIP-Rectification works to South Kakkad	19.6 1.5 1.5 1.5 1.5 20	ongoing .Nearing completion Completed Work completed.
2 1 2 3 4 5	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP - Mulakkulam Branch canal - Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP - South Kakkad Distributory- Removel of slipped earth at various chainages SDRF - MVIP - Piravom branch canal - Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF - MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at ch. 1100m and 3210m SDRF-MVIP-Rectification works to South Kakkad Distributory at various chainages between Ch. 1850M and Distributory at various chainages Distributory at various chainages Distributory at various chainages Distributory at various chainages Distributory at various chai	19.6 1.5 1.5 1.5 1.5 20	ongoing .Nearing completion Completed Work completed.
2 1 2 3 4 5 6	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at ch. 1100m and 3210m SDRF-MVIP-Rectification works to South Kakkad Distributory at various chainages between Ch. 1850M and 2000m, 2330m and 2430m and 2900m and 3050m	19.6 1.5 1.5 1.5 1.5 1.5 1.5	ongoing .Nearing completion Completed Work completed.
2 1 2 3 4 5 6 7	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal - Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at ch. 1100m and 3210m SDRF-MVIP-Rectification works to South Kakkad Distributory at various chainages between Ch. 1850M and 2000m, 2330m and 2430m and 2900m and 3050m SDRF- MVIP Desilting and urgent rectification works to the	19.6 1.5 1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed.
2 1 2 3 4 5 6	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal- Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at Ch. 1100m and 3210m SDRF-MVIP-Rectification works to South Kakkad Distributory at various chainages between Ch. 1850M and 2000m, 2330m and 2430m and 2900m and 3050m SDRF- MVIP Desilting and urgent rectification works to the damaged portion between Ch.0 m and 120.m of	19.6 1.5 1.5 1.5 1.5 1.5 1.6	ongoing Nearing completion Work completed. Work completed. Work completed. Work completed. Work completed. Work completed. Work completed. Work completed. Work completed. Work completed.
2 1 2 3 4 5 6 7	Municipality. Protection wall improvements to canal bund road of Koothattukulam Distributory (ch.6570m) near Puthuvely in Veliyannoor Panchayath SDRF- WORKS MVIP MVIP -Mulakkulam Branch canal -Removel of slipped earth and rectification between Ch.1625 m and 1675 m MVIP -South Kakkad Distributory- Removel of slipped earth at various chainages SDRF -MVIP- Piravom branch canal - Removel of slipped earth of at various chainages SDRF-MVIP- Koothattukulam distributory Rectification works between ch.3675 m and 3725 m SDRF-MVIP-Onakkor distributory-Removel of slipped earth at various chainages and rectification works between ch.1100to 1150.m Name of work:- SDRF-MVIP-Rectification works to Koothattukulam Distributory at various chainages between Ch. 2650M and 3470m SDRF -MVIP- Koothattukulam distributory- Rectification works to the spout and leading chanel at Ch. 2500m and rectification of spout at ch. 1100m and 3210m SDRF-MVIP-Rectification works to South Kakkad Distributory at various chainages between Ch. 1850M and 2000m, 2330m and 2430m and 2900m and 3050m SDRF- MVIP Desilting and urgent rectification works to the	19.6 1.5 1.5 1.5 1.5 1.5	ongoing Nearing completion Completed Work completed.

30.97

2328.435

10	SDRF- MVIP- Desilting and urgent rectification works to the damaged portion between Ch.4600. m and 4976m of Kuravilangadu distributory	1.5	Work completed.
11	SDRF- MVIP -Desilting and urgent rectification works to the damaged portion near Ch.600.m of Muttuchira distributory	1.5	Work completed.
12	SDRF-MVIP- Desilting works to the damaged portion between Ch.12450.m and 12950.m of Ettumanoor branch canal	1.5	Work completed.
13	SDRF-MVIP Desilting and urgent rectification works to the damaged portion between Ch.O.m and 800.m of Manjoor distributory.	1.5	Work completed.
14	SDRF-MVIP- Desilting works to the damaged portion between Ch.17000.m and 17500.m of Ettumanoor branch canal	1.5	Work completed.
15	SDRF-MVIP-Desilting and urgent rectification works to the damaged portion between Ch.750m & 1000.m, 1530m & 1800 m of Kattampak distributory	1.5	Work completed.
16	SDRF-MVIP- Desilting and urgent rectification works to the damaged portions between Ch.1000.m and 1500m, 3000m and 3425.m of of Valayam code distributory	1.5	Work completed.
17	SDRF- MVIP-Desilting of Cut And Cover and urgent rectification works of the damaged portion between Ch.0 m and 150.m of Kadappoor distributory	1.5	Work completed.
18	SDRF-MVIP- Rectification of spouts of Piravom branch canal and leading channel.	0.58	Work completed.
19	SDRF -MVIP- Rectification works to spout and leading channel at Ch.35485.M and 37100.M of LBMC	1.5	Work completed.
20	SDRF-MVIP-Rectification works to LBMC at various chainages between Ch. 32605M and 33700m	25	Work completed.
21	SDRF-MVIP-Rectification works to Peruva Distributory at various chainages between Ch. 500M and 950m	18.5	Work completed.
22	SDRF MVIP-Peruva Distributory - Rectification works between ch.50.m and 250.m .	1.5	Work completed.
23	SDRF - MVIP- Rectification works to spout and leading channel at Ch.33200.M of LBMC	1.5	Work completed.
24	SDRF MVIP- Rectification works to spout and leading channel at Ch.30888.M of LBMC	1.5	Work completed.
25	SDRF -MVIP- Rectification of leading channels from spouts at Ch. 1320.m, Ch.2000.m, Ch.2100.m, Ch. 2800.m, Ch.4200.m and Ch.5000.M and valve chamber at Ch.1320. M of Peruva distributory	0.64	Work completed.
26	MVIP -SDRF Works - Desilting and Rectification works todamaged lining due to flood between chainage 3500m and 4600m of Kuravilangadu distributory	4.5	Work completed.
	. MVIP - SDRF woks - Rectification works to damaged lining due to flood between chainage 1200m and 1800m of Kuravilangad distributory.	21	Work completed.
28	SDRF -MVIP- Urgent rectification works to the damaged portion between Ch. 1666 m and 1800 m of Ettumanoor distributory	1.5	Work completed.
29	SDRF-MVIP- Removel of broken parapet wall from canal and rectification near Ch. 700m of EBC and desilting works between ch.0 m and 2000m	1.5	Work completed.
30	MVIP - SDRF - Desilting and rectification works to damaged lining due to flood between Ch.10m and 385m of Kuravilangad distributory	14.4	Work completed.
31	MVIP -SDRF Works - Desilting and Rectification works to damaged lining due to flood between chainage 150m and 200m and 612m and 800m of Kadappoor distributory	9	Work completed.
32	MVIP - SDRF woks - Rectification works to damaged lining due to flood between chainage3750m and 4300.m of		Work

· }—	The state of the s		
33	2000m of Muttuchira distributory	12.41	Work completed.
34	1200m of Kuravilangadu distributory	10.5	Work completed.
35	and 3050m of Kadappoor distributory	12	Work completed.
36	2300m of Vilayamcode Distributory	4.5	Work completed.
37	SDRF MVIP -Urgent redtification works to the flood damaged portion between CH 7500 to 7748m of Kidangoor distributory	12	Work completed.
38	SDRF MVIP -Urgent rectification works to the flood damaged portion between CH 320 to 340 m, Ch 825-840 m, Ch 7300-7305m, Ch 950-990 and Ch 1130-1180 of Kurumulloor distributory	4.3	Work completed.
39	SDRF MVIP -Urgent Desilting and rectification works to the flood damaged portion between Ch 550-1665m, Ch 2050-2195, Ch 2355-2900, Ch 3150-3435, Ch3545-3626 and ch 3974-4046.4m of Ettumanoor distributory	7.4	Work completed.
40	SDRF - MVIP- Rectification of leading channels from spouts at CH.950.M, Ch.2400.M, CH.2600.M and Ch.3800.M of Mulakkulam branch canal	0.14	Work completed.
	PVIP		
1	PVIP-Rectification works near chi 1 5km of Thalalada Ma T		
2	The resemble teakage near the 1 4 km of Northean No.	1.50	Vork completed
3	portion of Karikode MD]	Vork completed
4	PVIP- Flood damage-rectification to prevent at ch: 10m of Thuruthikkara MD	ì	Vork completed
5	PVIP-SDRF-Rectification works near ch:5km to 10km of Edakkattuvayal MD PVIP-SDRF-Rectification works near ch:4.00 to 4.90 km of Edakkattuvayal MD	1	ork completed
		J	
7	PVIP-SDRF-Rectification works to Kalamboor FC	1.50 W	fork completed
8	I' '' YEADI 'DELUIILAHOD WOLKE DAAR Ch.Co. 4- 3 A31	1.50W	ork completed
9	PVIP-SDRF-Urgent Rectification works to the Nechoor FC	1.50 W	ork completed
10	PVIP-SDRF-Urgent Rectification works to the Nechoor FC No:2	1.50 w	ork completed
11	PVIP-SDRF-Urgent rectification works to the Amballoor FC	1.50 W	ork completed
12	ch: 0m to 100m	.5	ork completed
13	PVIP-SDRF-Removing excess silt for water distribution from ch	W	ork completed
14	500m to 900m of Kanijramahtam MD		ork completed
	PVIP-SDRF- Removing excess silt for water distribution from ch		ork completed
16	PVIP- SDRF - Removing excess silt for water distribution from ch 2km to 2.4km of Nechoor MD PVIP- SDRF- Rectification weeks constal 1.20		ork completed
18	PVIP- SDRF- Rectification works near ch 14.20km of Kolenchery Branch Carial scheme1 PVIP- SDRF- Rectification works to the leakage portion of Thalakode MD pear ch 600m		rk completed
10	PVIP- SDRF- Removing excess earth for water distribution	1.5 wo	rk completed
20	PVIP- SDRF- Removing excess earth for water dietails also for	1.5 wo	rk completed
<u></u>	ch 3.5km to 4.215km of Edakkattuvayal MD	1.5 Wo	rk completed

ch 4.5km to 5.215km of Edakkat	
22 PVIP-SDRF-Rectification works to MD near ch:1.500km	the leaked portion of Nechoor
PVIP-SDRF-Rectification works to MD near ch:3.300km	the leaked portion of Nechoor 2.1 Work completed

Chief-Engineer Project-ii

nwarant Brillard

13/1/21