## 14 -ാം കേരള നിയമസഭ

### 22 -ാം സമ്മേളനം

## <u>നക്ഷത്ര ചിഹ്നം ഇല്ലാത്ത ചോദ്യം നം. 2795</u>

<u>22-01-2021 - ൽ മറുപടിയ്ക്</u>

# തിരുവമ്പാടി ജലസേചന വകപ്പിനകീഴിലെ പ്രവൃത്തികൾ

ചോദ്യം		ഉത്തരം		
	ശ്രീ. ജോർജ് എം .തോമസ്	Shri. K. Krishnankutty (ജലവിഭവ വകപ്പുമന്ത്രി)		
(എ)	ഈ സർക്കാർ അധികാരത്തിൽ വന്നതിനുശേഷം ജലസേചന വകുപ്പിന് കീഴിൽ തിരുവമ്പാടി മണ്ഡലത്തിൽ അനുവദിച്ച പ്രവൃത്തികളും അവയുടെ പുരോഗതിയും വിശദമാക്കുമോ;	(എ)	ജലസേചന വകുപ്പിന് കീഴിൽ തിരുവമ്പാടി മണ്ഡലത്തിൽ അനുവദിച്ച പ്രവൃത്തികളും അവയുടെ പുരോഗതിയും സംബന്ധിച്ച വിവരം അനുബന്ധമായി ചേർക്കുന്നു.	
(ബി)	തൊണ്ടിമ്മൽ റെഗുലേറ്റർ കം ബ്രിഡ്ജിന്റെ വിശദാംശം ലഭ്യമാക്കുമോ?	(ബി)	തൊണ്ടിമ്മൽ റെഗുലേറ്റർ കം ബ്രിഡ്ജ് പ്രവർത്തികമാക്കുന്നതിനുള്ള സാധ്യതാ പഠനത്തിന് 4.60 ലക്ഷം രൂപയുടെ അംഗീകാരം നൽകുകയും സാധ്യതാ പഠനം നടത്തി റിപ്പോർട്ട് ഡിസൈൻ ലഭ്യമാക്കുന്നതിന് ചീഫ് എഞ്ചിനീയർ ഐ.ഡി.ആർ.ബിക്ക് സമർപ്പിച്ചിട്ടുണ്ട്. ഡിസൈൻ ലഭ്യമായാൽ തൊണ്ടിമ്മൽ റെഗുലേറ്റർ കം ബ്രിഡ്ജിന്റെ DPR തയ്യാറാക്കി തുടർനടപടികൾ സീകരിക്കുന്നതാണ്.	

സെക്ഷൻ ഓഫീസർ

# അനുബന്ധം

Sl. No.	Name of Work	Amount (in lakh)	Status of work
1	Protecting the left bank of Iruvanhipuzha near Thazhemuripalli in Ward No. 1 of Kodiyathur Panchayath	23.50	work completed
2	Investigation for the construction of Regulator cum bridge at Chullikkattu kadavu at Iruvanhipuzha in Kodenchery panchayath	4.40	work completed
	Investigation for the construction of Regulator cum bridge at Pathankayam across Iruvanhipuzha in Kodenchery panchayath	4.75	work completed
4	Protecting the left bank of Iruvanhipuzha at Kaliyampuzha in Thiruvambady Panchaayath	13.25	work completed
5	Protecting the left bank ofChalipuzha at Thekkumthottam in Kodenchery Panchaayath	23.00	work completed
6	Protecting the left bank of Iruvanhipuzha near Pullooramparathuruth in Thiruvambady Panchayath.	45.00	Material collection started
7	Urgent Rectification to damaged side protection wall on D/S of Pulikkayam Checkdam in Kodenchery Panchayath . (State Disaster Response fund-Dist.Collector, Kozhikkode)	2.85	work completed
8	Investigation Estimate for Regulator Cum Bridge at Thondimmalkadavu in Mukkam Municipality.	4.60	Work Completed.
9	Protecting the left bank of Iruvanhipuzha D/S of Mukkam bridge along Chonad road in Karassery Panchayath	45.00	Work in Progress
10	Rectification of the left bank of Iruvanhipuzha at upstream side of Mukkam kadavu bridge in Karassery Panchayath	26.00	work completed
- 1	Rectification of the left bank of Iruvanhipuzha at Palakkadavath koodangara paramba in Karassery Panchayath	19.00	work completed
12	Rectification of left bank of Iruvanhipuzha near veran kadavu road at chakkingal in Kodiyathur panchayath	12.00	work completed
	Rectification of the Right bank of Iruvanhipuzha upstream of Theyyathumkadavu bridge at Thrikkaythil in Mukkam Muncipality	28.00	work completed
14	Rectification of the right bank of Mukkam cherupuzha at Palakkathottil in Karassery panchayath	23.00	work completed

8-3-4

29	Urgent repair to Payona VCB in Kakkavayal thodu in Puthuppadi Panchayath	7.00	the contractor on 18/03/2020	
	Manalvayal VCB in Puthuppadi Panchayath	7.00	60% completed  Site handed over to	
28	Urgent repair works of VCB cum bridge at	F.00		<b>&gt;</b>
27	Renovation of Lift Irrigation at Tharammal kadavu in Kodiyathoor Panchayath	25.00	Completed	-1-1
	Srambipoolakandi paramba in ward no 14 in Mukkam municipality	15.50	AS accorded	) 2-1-(
	Protecting the right bank of Iruvanhipuzha at			
25	Kozhipalliparamba near Cheruvadi in Kodiyathur Grama Panchayath	34.00	AS accorded	
25	Protecting the Right bank of Chaliyar River at	0.105		
	near Karamoola in Karassery Grama panchayath			
24	Karamoola Vallathayi cherupuzha at Palakkathottil	19.00	work in progress	
	S0289/20-21) Protection work to the right bank of		·	
	Koombara bazar in Koodaranji Panchayath Kozhikode Jilla Panchayath 2019-20(Project no	4.00 work		
23	Removal of boulders from Koompara river near	4.00	work completed	
22	Removal of debris and boulders from Koompara river near Koompara Tribal LP School at Koompara in Koodaranhi Panchayath	6.00	Work completed	
21	Iruvanhipuzha downstream of Elanthukadavu bridge in Thiruvambadi & Kodancheri Panchayath	30.00	work completed	ACTOR AND ANALYSIS OF THE PROPERTY OF THE PROP
	Removal of debris and boulders from			
	Iruvanhipuzha upstream of Elanthukadavu bridge . in Thiruvambadi Panchayath	18.00	work completed	
20	Removal of debris and boulders from	10.00	1 1 1	
	Panchayath			
19	Removal of debris and boulders from Chalipuzha downstream of Chembukadavu VCB in Kodancheri	20.00	75 % completed	
18	Panchayath	7.00	50 % completed.	1
18	Removal of debris and boulders from Chalipuzha	7.00	· !\	P-5
17	portion of Pullooramparathiruth in Thiurvambadi Panchayth	65.00	work in progress	· -
1-	Protecting the left bank of Iruvanhipuzha down stream of old Elanthukadavu bridge and at end		_	
16	Parayangad Bhagavathi Temple in Ward No.10 of Kodiyathur Grama Panchayat	48.00	Site handed over	
	Grama Panchayath Protecting the Right bank of Chaliyar river near			
15	Kundumkadavu at Tharammal in Kodiyathur	25.00	work completed	
	Rectification of the right bank of Chaliyar river near			7

· Is	The Parabickal VCP at Vakkad in		
211	Urgnet repairs to Panchickal VCB at Kakkad in	7.00	60% completed
	Puthuppadi Panchayath Construction of check dam in Venchery river in	00.00	Tayle atouted
~ 1 1	Puthuppadi panchayath	80.00	Work started
	Construction of Lift Irrigation Scheme at	105.00	Tenderd, no response,
	Maliyakkal in Karasseri Panchayath	125.00	re-tendered
	Urgent repairs to VCB at Malappuram Ambalappadi		Site handed over to
33	Kappadu Vennottil in Puthuppadi Panchayath	25.00	the contractor on 03/09/2020
			05/05/2020
	Construction of VCB across Kallanpullu thodu in	75.00	Agreement executed
34	Koompara pallikkadavil in Ward No.3 of Koodanji	75.00	1-8
	Panchayath Renovation of L.I.Scheme at Tharammal kadavu		1.1
35	and canal extension in Kodiyathoor Panchayath	25.00	Completed
	Protection of left bank of Nooramthodu at Edapatta		Completed
36	Kurukkalil in Kodanchery Panachayath	9.00	Completed
	Protecting the bank of Kilayil Uppoothikkunnu	15.5	Commisted
37	thodu in Puthupadi Panchayath	17.5	Completed
	Renovation of Tharammal kadavu from		
38	Kuttukkattummal to Chali and canal extension in	20.00	Work in progress
50	Kodiyathoor Panchayath		
	Protecting the left bank of Vallathayiapara VCB in	5.00	Completed
39	Karassery Panchayath	3.00	Completed
	Protecting the left bank of Peruvampoyil thodu		
40	near government U.P.School at thottum mukkathu	9.00	Completed
	in Kodiyathoor Panchayath.		
<b>-</b>	Construction of tractor way in Cheruvadi	7.8	Completed
41	punchappadam in Kodiyathoor Grama Panchayath	7.0	
			Site handed over to
42	Protecting the bank of Pottikkayi Thadayana	25.00	the contractor on
	mukku thodu in Puthuppadi Panchayath		22/02/2020
-	Protecting the bank of Eruthili puzha near		
43	upstream and down stream of Kannappankundu	40.00	75% Completed
	VCB in Puthuppadi Panchayath.		
	Protection of left bank of Peechampoyil thodu at	9.00	Completed
44	Vallayippara in Karassery Panchayath	9.00	Completed
	Renovation of Velluvaval Padashekharam in	45.00	Completed
45	Kodanchery panchayath		Compactor
	SDRF - Urgent restoration of bunds of Pathippara -		
46	Kakkavayal thodu on u/s of Kakkavayal VCB		
	and the second second	10.00	Work completed,
	Panchayath of Thiruvambadi LA/Kozhikode		
	District.		
47	C1 de af Dama childreal	8.50	Work completed

87.4

	thodu at Kakkad in Puthuppadi Panchayath of			
	Thiruvambady LA/Kozhikode District			
	SDRF-Urgent restoration works to collapsed beams			
48	of Parappanpara KannappanKundu thodu in	12.10	work completed	
	Puthuppady Panchayath,			
	ThiruvambadyLA/Kozhikode			
	SDRF-Flood Damage Urgent Repair to the existing	4.30	Work completed	
49	protection at Muringathodu in Thiruvampady			
	panchayath		3.44	
	SDRF-Flood Damage Protection of River near			
50	Pushpagiri VCB near Kurushupally Kudaranhi	11.9	Work completed	
	Panchayat			
51	SDRF-Flood Damage Urgent Repair works to the	6.10	Work completed	
	Right Bank of koompara river near Koompara			
	Bazar in koodarnji panchayath			
	SDRF-Flood Damage Urgent Rectifiction of river		_	
52	mouth of Pulparamba Edolipali Manassery thodu	7.30	Agreement executed	
	in Mukkom Municipality			
	SDRF-Flood damages-Urgent Desilting from D/s of			
53	Kannappankundu VCB in Pathippara, Kakkavayal	9.00	Droppeed	
	VCB cum bridge in Kakkavayal in Puthuppadi			
	Panchayath, Kozhikode Dt			
54	SDRF- Flood Damages Urgent De-silting of Chamal		Dropped	
	thodu in Kattippara and Puthuppadi Panchayat	9.00		
	Kozhikode Dt			

3.01.21

19/1/21

Hali