

**15 -ാം കേരള നിയമസഭ**

**7 -ാം സമ്മേളനം**

**നക്ഷത്ര ചിഹ്നം ഇല്ലാത്ത ചോദ്യം നം. 1074**

**07-12-2022 - ൽ മറുപടിയ്ക്ക്**

**അരൂർ മണ്ഡലത്തിലെ ജലവിഭവ വകുപ്പ് പദ്ധതികൾ**

ചോദ്യം		ഉത്തരം	
ശ്രീമതി ദൈവിമ		ശ്രീ. റോഷി അഗസ്റ്റിൻ (ജലവിഭവ വകുപ്പ് മന്ത്രി)	
(എ)	ജലവിഭവ വകുപ്പ് മുഖേന അരൂർ മണ്ഡലത്തിൽ 2020-21, 2021-22 , 2022-23 എന്നീ വർഷങ്ങളിൽ അനുവദിച്ച പദ്ധതികൾ ഏതെല്ലാമെന്ന് വിശദമാക്കുമോ;	(എ)	ജലവിഭവ വകുപ്പ് മുഖേന അരൂർ മണ്ഡലത്തിൽ 2020-21, 2021-22, 2022-23 എന്നീ വർഷങ്ങളിൽ അനുവദിച്ച പദ്ധതികളും പ്രസ്തുത പദ്ധതികളുടെ നിലവിലെ നിർമ്മാണ പുരോഗതി സംബന്ധിച്ച വിശദാംശങ്ങളും അനുബന്ധമായി ചേർക്കുന്നു.
(ബി)	പ്രസ്തുത പ്രവൃത്തികളുടെ നിലവിലെ നിർമ്മാണ പുരോഗതി വിശദമാക്കുമോ?	(ബി)	ജലവിഭവ വകുപ്പ് മുഖേന അരൂർ മണ്ഡലത്തിൽ 2020-21, 2021-22, 2022-23 എന്നീ വർഷങ്ങളിൽ അനുവദിച്ച പദ്ധതികളും പ്രസ്തുത പദ്ധതികളുടെ നിലവിലെ നിർമ്മാണ പുരോഗതി സംബന്ധിച്ച വിശദാംശങ്ങളും അനുബന്ധമായി ചേർക്കുന്നു.

സെക്ഷൻ ഓഫീസർ

**അനുബന്ധം**

**മാനേജിംഗ് ഡയറക്ടർ, കേരള വാട്ടർ അതോറിറ്റി കീഴിലെ പദ്ധതികൾ**

**ജൽജീവൻ മിഷൻ പദ്ധതികൾ**

പഞ്ചായത്ത്	AS 2020-21	AS 2021-22	As Total	FHTC Target	FHTC Given
അരൂർ	44.8	192.27	237.07	1180	1141
അരൂർക്കുറ്റി	207.1	-	207.1	1637	900
പള്ളിപ്പുറം	471.6	-	471.6	4401	2488
എഴുപ്പുന്ന	232.4	-	232.4	1741	1037
കോടംതരുത്ത്	186.5	-	186.05	1449	1101
കുത്തിയതോട്	245.1	-	245.1	1840	1288
പാണാവള്ളി	795.1	-	795.1	7408	2834
പെരുമ്പള്ളം	218.8	-	218.8	1912	1250
തൈക്കാട്ടുശ്ശേരി	182	-	182	1455	1395
തുറവൂർ	316	187.58	503.58	2352	2459
ആകെ	2899.4	379.85	3279.25	25375	15893

ഡെപ്യൂട്ടി സീനിയർ / എം.പി എൽഡി/ സ്റ്റേറ്റ് പ്ലാൻ			
Project Name	Year	Status	Project Work Status
State plan - 2021-22-JICA Scheme - Maintenance of OHSR at Panavally and Perumbalam-Painting the OHSR at Panavally and Perumbalam	2021-22	100	Completed
MPLAD-2018-19-Supply , erection, testing & commissioning of Skid Mounted 250LPH output Capacity R O Plant Capable of remove TDS upto 2000 PPM with all accessories in GHS Chandiroor	2018-19	100	Completed

Deposit work - PWD deposit Utility Shifting- The existing 90mm PVC Line sifting to the side of the newly formed approach road (Line-1) of the Vakkayil Bridge and across the Thodu ( Line-2) along the Helapuram –Moolekkalam Road in Thuravoor Panchayath	2021- 22	100	Completed
State Plan Scheme (2021-22)- Maintenance of OHSR at Arookutty and Pallipuram Grama Panchayath	2021- 22	100	Completed
Deposit work - Panavally Panchayat- Providing non domestic water connection to M .C .F in Panavally Panchayat.	2021- 22	100	Completed
Deposit work – District Panchayath – Alappuzha 2020-21 (Project No.5006/21) – Aroor Division – Supply and laying 90mm PVC pipe 975 meter at Thyil area in ward No.21 and Kummayithara area in ward 14 Aroor panchayath and Cheemamthara area in ward No.3 and Poojavely area in ward No13 of Thuravoor Panchayth	2021- 22	30	Agreement Executed
Deposit work – Project No..2/2022 - Pattanakkad Block Panchayat- 2022-23 – pipe line extension in Idamthuruth Vadakkekad area in ward No.17 of Thuravvor GP	2022- 23	30	Tender work progress
Deposit Work 2022-23 Thycattussery Panchayath – Disconnection of public tap in Thycattussery Panchayath	2022- 23	30	Tender Work progress

**ചിഫ് എഞ്ചിനീയർ, കട്ടനാട് പാക്കേജിന് കീഴിലെ പദ്ധതികൾ**

No	Name of Work	T.S.Amount in Lakhs	Stage of work
<b>WORKS ALREADY ARRANGED (PLAN SCHEME 2020-21)</b>			
1	KP- Mitigation of flood damages-Desilting of Meenkuzhi thodu in ward No. 2 of Arookutty Panchayath	16.57	Work completed(100%)Final bill submitted.
2	KP-Mitigation of Flood damages- Desilting and Cleaning of Thoni thodu in Ward No. 5,6,7,11,and 12 Of Thuravoor Panchayath	13.80	Work completed(100%)Final bill submitted.
3	KP-Mitigation of flood damages- Desilting and cleaning of Karalam thodu in Ward No. 13, 14 and 15 of Thuravoor Panchayath	15.90	Work completed(100%)Final bill submitted.
4	KP-Mitigation of flood damges -Desilting and Cleaning of Kavil thodu in ward No. 5,6, 11,12 and 13 of Thuravoor Panchayath	19.90	Work completed(100%)Final bill submitted.
5	KP- Mitigation of Flood Damages-Desilting and Cleaning of Desathodu in ward No.3,4,13 and 14 of Thuravoor Panchayath	8.69	Work completed(100%)Final bill submitted.
6	KP-Mitigation of Flood damages- Desilting and Cleaning of Mooppanthara Thodu in Aroor Panchayath	4.00	Work completed(100%)Final bill submitted.
7	KP- Mitigation of Flood Damages-Desilting and Cleaning of Karethodu in ward No.2 of Kuthiyathodu Panchayath	11.6	Work completed(100%)Final bill submitted.
8	KP-Mitigation of flood damages-Desilting and cleaning of Desa thodu from Arackal Palam to Karalam thodu in ward no. 14 & 15 Thuravoor panchayath.	14.20	Work completed(100%)Final bill submitted.
9	KP-Mitigation of flood damages-Construction of retaining wall in Perumparackal thodu in ward no.3 of ChennampallipuramPanchayath.	16	Work completed(100%)Final bill submitted.
	<b>TOTAL</b>	<b>120.66</b>	

<b>WORKS ALREADY ARRANGED (PLAN SCHEME 2021-22)</b>			
1	Providing and protection work at both bank of changaram thodu near east side of changaram bridge in Kuthiyathodu and Kodamthuruthu Pts	35.9	Work completed(100%)Final bill submitted.
2	KP-Mitigation of flood damages to Annala thodu in Panavally panchayath	7.8	55%
	<b>TOTAL</b>	<b>43.7</b>	
<b>WORKS ALREADY ARRANGED (PLAN SCHEME 2022-23)</b>			
1	GENERAL-Outer bund at moolekalam Thuavoor -Construction of outer bund at moolekalam Pozhichaal Thuravoor Grama Panchayath ward 15-General Civil Work	4.20	S.N.Issued
	<b>GRAND TOTAL</b>	<b>168.56</b>	

### **SDRF DETAILS 2020-21**

1	Rectification of flood Damages -Desilting of thodu from Vallyara culvert to south (illathu thodu) Thykkattusery panchayath	3.99	work completed and Bill submitted
2	Rectification of flood damages desilting of Vallyara -Chooramana Thodu from Vallyara culvert to Koppayil kayal in Thykkattusery panchayath in ward No.2	3.52	work completed and Bill submitted
3	KP-Rectification of flood damages- Desilting of Ellikkatu Chathanadu thodu in Ward No 3 of Thykkattusery panchayath	5.6	work completed and Bill submitted
4	KP-Rectification of flood damages-Desilting of Kurussukadavu-Puthuppally thodu in ward no 13 of Thycattusseri panchayath	2.3	work completed and Bill submitted
5	KP-Rectification of flood damages-Desilting of Thazhu thuruth-Chittezhathu thodu in ward no 1 of Thycattusseri Panchayath	3.5	work completed and Bill submitted

6	KP-Rectification of flood damages -Desilting of Chellikkadu Theveli thodu in Ward no 2 of Arookutty panchayath	4.9	work completed and Bill submitted
7	KP-Rectification of flood damages- Desilting of Maniyanppally thodu in ward No.10 of Arookutty panchayath.	6.6	work completed and Bill submitted
8	KP- Rectification of flood damages- Desilting of Kinath kumbel Iranikkal thodu in Ward No.2 of Arookutty panchayath	10.3	work completed and Bill submitted
9	SDRF-KP- Desilting of link thodu (in between Perumbarackalthodu and Kalathil thodu) in Perumbarackal Padashekham in Chennam pallippuram Panchayath.	1.9	work completed and Bill submitted
10	SDRF- KP-Desilting of Chirakkal Thodu from Aarattukulam in ward no.12 of Panavally Panchayath	3.3	work completed and Bill submitted
<b>SDRF DETAILS 2021-22</b>			
1	SDRF-Desilting of Varyamparambu Pallithodu in ward No.13 of Thykkattussery Panchayath	4.0	work completed and Bill submitted
2	SDRF- Rectification of flood damages -Desilting and Cleaning of Millukadavu in ward no 1 &13 of Arookutty panchayath	3.0	work completed and Bill submitted
3	SDRF-Desilting and cleaning of Chanthuruthil thodu ward 6 in Thuravoor panchayath	4.0	work completed and Bill submitted
4	SDRF-Desilting and cleaning of Vadasseri vedamparampu thodu ward no. 8 & 9 of Thuravoor Panchayath	3.6	work completed and Bill submitted
5	SDRF-Desilting and cleaning of Pattamchira thod in ward no .16 of Thuravoor grama panchayath	3.4	work completed and Bill submitted
6	SDRF Mitigation of flood damages desilting of Vadakkekadu colony thodu upto pozhichal in ward no 17 and Thoppuvinte thodu in ward No18 of Thuravoor panchayath	5.0	work completed and Bill submitted

7	SDRF-Desilting and cleaning of Changaram thodu in ward no 4 of Kuthiyathodu panchayath	4.0	work completed and Bill submitted
8	SDRF Mitigation of flood damages desilting of Desa thodu south portion from Desa thodu palam to Kurumbi kayal in ward no.4 of Thuravoor and ward no 12 Kuthiyathodu panchayath	5.0	work completed and Bill submitted
9	SDRF-Desilting and cleaning of Thypirampuchakkaalchira thodu in Kodamthuruth panchayath ward 4	1.0	work completed and Bill submitted
10	SDRF -KP-Desilting of Kottarappararambu medayil thodu in ward no.8 and 9 of Panavally Panchayath	7.00	work completed and Bill submitted
11	SDRF -KP-Desilting of Munnu thodu in ward no.17 of Chennam pallippuram Panchayath	5.00	work completed and Bill submitted
	<b>TOTAL</b>	<b>45.0</b>	

**ചീഫ് എഞ്ചിനീയർ (ജലസേചനവും ഭരണവും) നു കീഴിലെ പദ്ധതികൾ**

<b>2020-2021</b>			
Sl. No.	Name of Work	TS Amount	Work Status
1	2020/4034/IA- Investigation estimate of construction of foot bridge across Kakkathuruth Kayal from Kakkathuruthu ferry to Kakkathuruthu island in Ezhupunna Panchayath of aroor LAC	3,70,000/-	Completed

<b>2021-2022</b>			
Sl. No.	Name of Work	TS Amount	Work Status
2	2021/1862/IA-NC/ASE 2021-Urgent protection work using Geo bag between CESEP No.961 &962 between CH 192400Km and 192.60Km at Kairali stop in Thravoor Panchayath of Aroor LAC (4 Layers of Geo bag	10,00,000/-	Completed
3	2021/5905/IA Deposit work-Protection works with cover slabs to Shasthamveli-Shanmughapuram thodu in Perumbalam Panchayath of Aroor LAC	15,24,200/-	On going