

15 -ാം കേരള നിയമസഭ

8 -ാം സമ്മേളനം

നക്ഷത്ര ചിഹ്നം ഇല്ലാത്ത ചോദ്യം നം. 1004

06-02-2023 - ൽ മറുപടിയ്ക്ക്


പുത്താർ മണ്ഡലത്തിലെ ഇറിഗേഷൻ പദ്ധതികൾ

ചോദ്യം		ഉത്തരം	
ശ്രീ. സെബാസ്റ്റ്യൻ കുളത്തുകൽ		ശ്രീ. റോഷി അഗസ്റ്റിൻ (ജലവിഭവ വകുപ്പ് മന്ത്രി)	
(എ)	ഈ സർക്കാർ അധികാരത്തിൽ വന്നശേഷം പുത്താർ മണ്ഡലത്തിൽ നടപ്പാക്കുന്ന മൈനർ/മേജർ ഇറിഗേഷൻ പദ്ധതികളുടെ വിശദവിവരം ലഭ്യമാക്കാമോ;	(എ)	വിശദാംശങ്ങൾ അനുബന്ധമായി ചേർക്കുന്നു.
(ബി)	പ്രസ്തുത പദ്ധതികളുടെ നിലവിലെ സ്ഥിതി സംബന്ധിച്ച വിശദാംശം ലഭ്യമാക്കുമോ?	(ബി)	വിശദാംശങ്ങൾ അനുബന്ധമായി ചേർക്കുന്നു.

സെക്ഷൻ ഓഫീസർ

14	Protecting the damaged right bank of Pamba river at moolakkayam bhagom near Thoniyamkuzhy house in Ward no.12 of Erumely Panchayath	23.90	Work Not started
15	Protection of damaged bathing ghat at Orumkal kadavu- Protection of damaged bathing ghat near bridge at Orumkal kadavu in Manimala river	16.99	Work Tendered
16	Protecting the right bank of Pullakayar near in sy no.214/3-10 at Enthayar Kappilammood in Koottickal Panchayat of Poonjar Constituency.	13.50	Work Completed
17	Protecting the right bank of Pullakayar d/s of Mukkulam - Enthayar bridge in Koottickal Panchayath-	9.20	Work Completed
18	Dismantling the damaged checkdam at Koottickal in Poonjar constituency.	7.70	Work Completed
19	Protecting the left bank of Meenachil river(Poonjar river) downstream of Thadavanal Bridge in Ward No. 21 of Erattupetta Municipality-	55.00	78% work Completed.
20	Protecting the banks of Chettu thodu near Bhajana Madom colony in ward no.8 of Thidanadu panchayath	3.50	Site handed over. work could not be started due to heavy flow in thodu
21	Maintenance of Thanninal vathil-Kottaram kadavu checkdam in Thidanad Panchayath	12.00	Site handed over. work could not be started due to heavy flow in thodu
22	Protecting the banks of Kadaladimatam thodu near laksham veedu colony in ward No:12 of Poonjar Thekkekkara Panchayath.	1.50	Work completed.
23	Side protection works to Thalapra thodu near Thalapra colony road in ward No.VIII of Poonjar Thekkekkara Panchayath.	24.80	Site handed over. work could not be started due to heavy flow in thodu
24	Protecting the bank of Kudikkani thodu near Chemmalamattom in Thidanadu Panchayath	13.80	Work completed
25	Urgent Removal of deposited silt & debris- Kootickal & Kokkayar Panchayaths	13.59	Work completed
26	Repair works to Kulamakkal check dam across Manjalaruvi thodu in mundakkayam Panchayath	11.69	work in progress
27	Rectification work to the side of Puthen chantha thodu near sy no.385/1 in ward No. Mundakkayam Panchayath	5.53	Work closed
28	Emergency Removal of Debris and Obstructions at U/S, D/S and under Koratti bridge.	3.32	completed

29	Emergency Removal of Debris and Obstructions at U/S, D/S and under Karimpu kayam causeway.	3.33	completed
30	Urgent removal of deposit silt and debris in Manimala river basin at Mundakyam, Erumely pt.	10.83	completed
31	Protecting the side of Edakkunnam thodu in Mukkalybhagom in ward No. 15 of Edakkunnam Panchayathu.	8.03	completed
Total		325.62	


 സെക്ഷൻ ഓഫീസർ