

15 -ാം കേരള നിയമസഭ

8 -ാം സമ്മേളനം

നക്ഷത്ര ചിഹ്നം ഇല്ലാത്ത ചോദ്യം നം. 1065

06-02-2023 - ൽ മറുപടിയ്ക്ക്

കായംകുളം മണ്ഡലത്തിലെ ഇറിഗേഷൻ പ്രവൃത്തികൾ

ചോദ്യം		ഉത്തരം	
ശ്രീമതി യു പ്രതിഭ		ശ്രീ. റോഷി അഗസ്റ്റിൻ (ജലവിഭവ വകുപ്പ് മന്ത്രി)	
(എ)	2016 മുതൽ നാളിതുവരെ കായംകുളം മണ്ഡലത്തിൽ ജലസേചന (മൈനർ/മേജർ) വകുപ്പ് വഴി നടപ്പിലാക്കിയ പ്രവൃത്തികളുടെ വിശദാംശം ലഭ്യമാക്കാമോ?	(എ)	2016 മുതൽ നാളിതുവരെ കായംകുളം മണ്ഡലത്തിൽ ജലസേചന (മൈനർ/ മേജർ) വകുപ്പ് വഴി നടപ്പിലാക്കിയ പ്രവൃത്തികളുടെ വിശദാംശം അനുബന്ധമായി ചേർത്തിരിക്കുന്നു.

സെക്ഷൻ ഓഫീസർ

അനുബന്ധം

ജലസേചനവും ഭരണവും

മൈനർ ഇറിഗേഷൻ

2016-17

Sl. No.	Name of Work	Amount in Lakhs	Remarks
1	Construction of Orumuttu in Kandalloor Panchayath for the year 2016-17 Part 1	1.500	Completed
2	Construction of Orumuttu in Kandalloor Panchayath for the year 2016-17 Part 2	0.900	Completed
3	Annual maintenance of PI work under MI section in KayamkulamGovindamuttom regulator in Kayamkulam Municipality	3.260	Completed
4	Annual maintenance of PI work under MI section in KayamkulamValiya Pathiyoor Regulator near Valiya Pathiyoor Temple in Pathiyoor Grama Panchayath	0.670	Completed
5	Annual maintenance of PI work under MI section in Kayamkulam Pathiyoor Regulator in Pathiyoor Panchayath	3.040	Completed
6	Annual maintenance of PI work under MI section in Kayamkulam Karipuzha Regulator west of Karipuzha bridge and putting up cross bund across Pathiyoor thodu for preventing the entry of saline water to Pathiyoor Ullittapuncha in Cheppad Panchayath	2.590	Completed

2017-18

Sl. No.	Name of Work	Amount	Remarks
1	Annual Maintenance of P.I. Works under M.I. Section, Kayamkulam for the year 2017-18 - Providing tidal bund across natural drains in Kandalloor Panchayath	1.300	Completed
2	Annual Maintenance of P.I. Works under M.I. Section, Kayamkulam for the year 2017-18 - Providing tidal bund placing shutter planks in the grooves of Valiya Pathiyoor Regulator near Valiya Pathiyoor Temple in Pathiyoor Panchayath	2.000	Completed

3	Annual Maintenance of P.I. Works under M.I. Section, Kayamkulam for the year 2017-18 - Providing tidal bund in Karipuzha Regulator west of Karipuzha bridge and putting cross bund across Pathiyoor thodu and other small natural drains to prevent salinity intrusion in Ullittapuncha in Cheppad Panchayath	5.000	Completed
4	Annual Maintenance of P.I. Works under M.I. Section, Kayamkulam for the year 2017-18 - Providing tidal bund using shutter planks and earth in grooves of Pathiyoor regulator near Eruva Sreekrishna Swamy Temple across Karipuzha thodu in Pathiyoor Panchayath	4.130	Completed
5	Annual Maintenance of P.I. Works under M.I. Section, Kayamkulam for the year 2017-18 - Providing tidal bund using shutter planks and earth in the existing grooves of Muttel Palam in Kayamkulam Municipality	3.600	Completed
6	P.M. Side protection works of Karipuzha thodu near Market bridge in Kayamkulam Municipality	28.000	Completed

2018-19

Sl. No.	Name of Work	Amount	Remarks
1	Maintenance of Works under M.I. Section, Kayamkulam for the year 2018-19 - Providing tidal bunds across natural drains in Kandallor Panchayath	0.550	Work Completed
2	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2018-19 by placing shutter planks in the grooves of Valiya Pathiyoor Regulator near Valiya Pathiyoor Temple in Pathiyoor Panchayath	1.490	Work Completed
3	Maintenance of Works under M.I. Section, Kayamkulam for the year 2018-19 - Providing tidal bund Karipuzha Regulator west of Karipuzha bridge and putting up cross bund across Pathiyoor thodu preventing the entry of salinity water to Pathiyoor Ullittapuncha in Cheppad Panchayath	3.170	Work Completed
4	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2018-19 near Eruva Sreekrishna Swami Temple across Karipuzha thodu in Pathiyoor Panchayath	0.550	Work Completed
5	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2018-19 Govindamuttom regulator in Kayamkulam Municipality	0.550	Work Completed
6	F.D. Renovation of Ozhukkunneetil thodu in Ward No. 4 of Kayamkulam Municipality	15.000	Work Completed

7	Renovation of Malayan canal in Kayamkulam Municipality ward No. 30 (Reach 1)	20.000	Work Completed
8	P.M. Side protection works of karipuzha thodu near market in Kayamkulam Municipality	28.000	Work Completed
9	FD Providing protection works to the sides of Punchakkala-Thattavazhy thodu from south of Puthur towards Illathu kizhakku in ward no. 12 and 13 of Chettikulangara Panchayath.	28.400	Work Completed
10	Side protection work of Anthikkattuchira in krishnapuram Panchayath	1.120	Work Completed
11	Renovation of chalumpattuchal in cheppad Panchayath	2.260	Work Completed

2019-20

Sl. No.	Name of Work	Amount	Remarks
1	Maintenance of Works under M.I. Section, Kayamkulam for the year 2019-20 - Providing tidal bunds across natural drains in Kandalloor Panchayath	2.220	Work Completed
2	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2019-20 by placing shutter planks in the grooves of Valiya Pathiyoor Regulator near Valiya Pathiyoor Temple in Pathiyoor Panchayath	1.870	Work Completed
3	Maintenance of Works under M.I. Section, Kayamkulam for the year 2019-20 - Providing tidal bund Karipuzha Regulator west of Karipuzha bridge and putting up cross bund across Pathiyoor thodu preventing the entry of salinity water to Pathiyoor Ullittapuncha in Cheppad Panchayath	2.900	Work Completed
4	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2019-20 near Eruva Sreekrishna Swami Temple across Karipuzha thodu in Pathiyoor Panchayath	1.600	Work Completed
5	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2019-20 Govindamuttom regulator in Kayamkulam Municipality	2.220	Work Completed
6	F.D. Protection work of Malayan canal in Kayamkulam Municipality ward No. 29	20.000	Work Completed
7	P.M. Renovation of Ozhukkunneetil thodu in ward No. 4 of Kayamkulam Municipality	15.000	Work Completed
8	Renovation of Puthukulangara Pond in ward No. 21 of Kayamkulam Municipality	45.000	Work Completed

2020-21

Sl. No.	Name of Work	Amount	Remarks
1	Maintenance of Works under M.I. Section, Kayamkulam for the year 2020-21 - Providing tidal bunds across natural drains in Kandallor Panchayath	1.000	Work Completed
2	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2020-21 by placing shutter planks in the grooves of Valiya Pathiyoor Regulator near Valiya Pathiyoor Temple in Pathiyoor Panchayath	2.060	Work Completed
3	Maintenance of Works under M.I. Section, Kayamkulam for the year 2020-21 - Providing tidal bund Karipuzha Regulator west of Karipuzha bridge and putting up cross bund across Pathiyoor thodu preventing the entry of salinity water to Pathiyoor Ullittapuncha in Cheppad Panchayath	6.460	Work Completed
4	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2020-21 near Eruva Sreekrishna Swami Temple across Karipuzha thodu in Pathiyoor Panchayath	1.520	Work Completed
5	Maintenance of Works under M.I. Section, Kayamkulam providing tidal bund for the year 2020-21 Govindamuttom regulator in Kayamkulam Municipality	1.270	Work Completed
6	F.D. Providing sluice and shutter arrangement to Muthalakkuzhy chal in Thazha thodu at Ward No. 2 of Devikulangara Panchayath	25.000	Work Completed

2021-2022

Sl. No.	Name of Work	Amount	Remarks
1	Rectificatiion work for retaining wall of Aarukadamban thodu near santwanam charity trust in Krishnapuram Panchayath.	35.00	Agreement Executed, Work not started
2	Providing temporary tidal bunds for the year 2020-21 in Chingoli Pt.	1.30	Work Completed
3	Providing tidal bunds for the year 2020-21 in across various thodu in kandallor Pt.	1.00	Work Completed
4	Providing tidal bunds for the year 2020-21 near EruvaSree Krishna swami temple across Karippuzhathodu in Pathoyoor Pt..	1.52	Work Completed
5	Providing tidal bunds for the year 2020-21 iatGovindhamuttom Regulator in kayamkulam Municipality	1.27	Work Completed

6	Providing tidal bunds for the year 2020-21 at Valiya Pathyoor Regulator near Valiya Pathyoor temple and various thode in pathyoor Pt.	2.06	Work Completed
7	Providing tidal bunds for the year 2020-21 in various thodu to protect Ullittuncha in Cheppad Pt.	6.46	Work completed.

2022-2023

Sl. No.	Name of Work	Amount	Remarks
1	Putting up Tidal bund for the year 2022-23 in Chingoli Grama Panchayath.	1.520	Completed
2	Putting up Tidal bunds for the year 2022-23 near Eruva Sree Krishna Swami Temple across Karippuzha Thodu in Kayakulam Municipality	12.470	Work in Tender process
3	Putting up Tidal bund for the year 2022-2023 at Govindamuttom Regulator in Kayamkulam Municipality.	13.160	Work in Tender process
4	Putting up Tidal bund for the year 2022-23 in Kandallloor Grama Panchayath.	3.683	Completed
5	Putting up Tidal bund for the year 2022-23 in various thodu to protect Ullittapuncha of Cheppad	6.640	Completed
6	Putting up Tidal bund for the year 2022-23, 1 No Regulator and 4 Nos cross bund in Pathyoor	14.220	Work in Tender process
7	Putting up Tidal bund for the year 2022-23, 1 No Regulator in Karipuzha thodu near Kochupalam in Cheppad Panchayath.	4.740	Work in Tender process
8	Putting up Tidal bund for the year 2022-23 in Muthukulam Panchayath.	2.441	Work in Tender process

MI works (SDRF)

Sl No:	Name of work	Amount	Status of the work
1	SDRF -Rectification of inchakkal Mundakkal thodu in ward No. 39 of kayamkulam municipality	4.2	Work in progress

2	SDRF -Rectification of Vareneth thodu in ward No. 7 of krishnapuram panchayath	4.5	Completed
3	SDRF - Rectificationof of Thymeenathethil thodu in ward No 4 of Muthukulam Panchayath	4.8	Completed
4	SDRF - Rectificationof of Chamakandam karippuzha Kochupalam thodu in ward No. 6,7 nd 9 cheppadu panchayath	3.9	Completed
5	SDRF - Rectification of Pavoor thodu in ward No 1 & 15 of Devikulangara Panchayath	3.3	Completed
6	SDRF - Rectification of Veeravana Muttom thodu in ward No. 8,3,5 and 4in cheppadu Panchayath	4.2	Completed
7	SDRF - Rectification of Avanakkum thodu in ward No 9 of Cheppadu Panchayath	4.5	Completed
8	SDRF Repairs and rectification of Chirackal Thodu in Muthukulam Panchayath	3.0	Completed
9	SDRF Repairs and rectification of Koottuvathukkal kadavu in Devikulangara panchayath	4.8	Completed
10	SDRF Repairs and rectification of Maruthanattu Thodu in Kayamkulam Municipality	2.4	Completed
11	SDRF Repairs and rectification of Manattel Thodu in Pathiyoor Panchayath	4.8	Completed

മേജർ ഇറിഗേഷൻ

Sl. No.	Name of Work	Amount in Lakhs	Remarks
1.	Providing protecting work to the right bank to the Kayamkulam kayal in ward No.12 in devikulangara panchayath.	4.0	Completed