# പതിനാലാം കേരള നിയമസഭ പതിനെട്ടാം സമ്മേളനം

a.

നക്ഷത്രചിഹ്നമിടാത്ത ചോദ്യം നമ്പർ.896

നിയോജക

#### 05.02.2020 ലെ മറ്റപടി

## മൈനർ ഇറിഗേഷൻ പ്രവർത്തി

ശ്രീ.റോജി.എം.ജോൺ:

അങ്കമാലി

സർക്കാർ

ഇറിഗേഷൻ

,വെള്ളപ്പൊക്ക

പ്രവൃത്തികളടെ

ഫണ്ടിൽ

ഓരോ

പോദ്യം

(എ)

കെ.കൃഷ്ണൻകട്ടി (ജലവിവേ വകപ്പമന്ത്രി)

(എ)യും (ബി)യും

അധികാരത്തിൽ വന്ന ശേഷം അങ്കമാലി ഇറിഗേഷൻ മൈനർ വകപ്പ് സർക്കാർ പ്രവൃത്തികൾക്കായി .നോൺ പ്ലാൻ പ്ലാൻ ത്രടങ്ങി വിവിധ നിവാരണം ഇറിഗേഷൻ നൽകിയ ഭരണാന്മതി നിന്നും തകയും പേന്ദരം, ഭരണാനുമതി വെള്ളപ്പൊക്ക ശതമാനം പ്രവൃത്തിയും എത്ര പൂർത്തിയായെന്നതുമടക്കമുള്ള വിവരങ്ങൾ പട്ടിക ഫണ്ടിൽ തിരിച്ച് ലഭ്യമാക്കാമോ; 1

ഈ

മണ്ഡലത്തിൽ

പ്രവൃത്തികളിൽ നാളിതുവരെ ടെണ്ടർ (ബി) മേൽ ചെയ്യാത്തവ ഏതെല്ലാമെന്നും ടെണ്ടർ ചെയ്തിട്ടം പ്രവൃത്തികൾ ഏറ്റെടുക്കാത്തവ ഏതെല്ലാമെന്നും വ്യക്തമാക്കാമോ?

മണ്ഡലത്തിൽ ഈ നിയോജക അധ്രികാരത്തിൽ പന്ന േരപ്പം ഇറിഗേഷൻ മൈനർ വകപ്പ് പ്ലാൻ, പ്രവൃത്തികൾക്കായി പ്ലാൻ, നോൺ തുടങ്ങി വിവിധ നിവാരണം നല്ചിയ ഭരണാനുമതി നിന്നും പ്രവൃത്തികളുടെ വിശദ വിവരങ്ങളടങ്ങിയ പട്ടിക അന്ദബന്ധമായി ചേർത്തിരിക്കുന്നു.

സെക്ഷൻ ഓഫീസർ

മറുപടി

ι

	SDRF		
SI No	Name of work	AMOUNT IN LAKHS	Remarks
1	SDRF-2018-Urgent retification works to the Manickamangalam branch canal near 1/500 km of Avanamcodu LIS in ward 12 of Kałady Gramapanchayath	1.50	Completed
2	SDRF-2018 Retification works of main canal at various places of Avanamcodu Lift Irrigation Scheme	1.50	Completed
3	SDRF-2018-Rectification works of Manappattuchira Right bank canal in ward 4 near Mundangamattom Padam in Malayattoor-Neeleeswaram Gramapanchayath	1.50	Completed
4	SDRF-2018-Urgent rectification works to the damaged aqueduct near 0/50 km of Neeleeswaram No.2 LIS Canal in Malayattoor -Neeleeswaram Gramapanchayath.	1.50	Completed
5	SDRF-2018Urgent rectification of field channel near 1/000 km and 1/100 km of Nettinampilly LIS in ward 6 of Kalady Gramapanchayath	1.50	Completed
6	SDRF-2018Urgent rectification of field channel near 1/220 km and 1/350 km of Nettinampilly LIS in ward 6 of Kalady Gramapanchayath	1.50	Completed
7	SDRF 2018 – Rectification works of to field channel of Chalil chira in various places	<sup>7</sup> 1.50	Completed
8	SDRF 2018 – Rectification works of Malayattoor No.2 LIS canal near Colony road in ward no.11 of Malayattoor- Neeleeswaram Grama Panchayath	1.50	Completed
9	SDRF 2018–Rectification works of Malayattoor No.2 LIS canal near Thottuva - Colony road in ward no.11 of Malayattoor- Neeleeswaram Grama Panchayath	1.50	Completed
10	SDRF 2018–Rectification works of Malayattoor No.2 LIS canal near Colony road ch. 0/530m from thottva colony road in ward no.11 of Malayattoor- Neeleeswaram Grama Panchayat	1.50	Completed
11	SDRF 2018 – Rectification of damaged canal near 0/700m of Kottamamthodu LI scheme ward no.6 in Manjapra	1.50	Completed
	SDRF 2018-Rectification of damaged canal near 0/730m of Kottamamthodu LI scheme ward no.6 in Manjapra	1.50	Completed
	SDRF 2018 – Rectification of damaged canal near 0/760m of Kottamamthodu LI scheme ward no.6 in Manjapra	1.50	Completed
14	SDRF 2018 – Rectification of damaged canal near 0/790m of Kottamamthodu LI scheme ward no.6 in Manjapra	1.50	Completed
15	SDRF 2018 – Rectification of damaged canal near 0/810m of Kottamamthodu LI scheme ward no.6 in Manjapra	1.50	Completed
16	SDRF 2018 -19 Rectification works to the Nayathodu LIS canal at various places near ch:0/250 m	1.50	Completed
17	Rectification work to Nayathod LIS canal near ch:0/50 m from Pump house	1.50	Completed

Õ

<del></del>			
18	ODRF 2018 -19 Rectification works to the field channel of Chalil chira near left side of the chira near ch:0/20m from the chira	1.50	Completed
19	SDRF 2018 -19 Rectification works of the field channel of Chalil chira near left bank of the chira	1.50	Completed
20	SDRF-2018-Rectification works of BM channel of Avanamcodu LI Scheme near Thevarmadam road	1.50	Completed
21	SDRF- 2018-19: Rectification works for the Manickamangalam branch canal of Avanamcode LIS near ch. 15.00m from culvert near enchakkal.	1.50	Completed
22	SDRF- 2018-19: Rectification works for the Manickamangalam branch canal of Avanamcode LIS near ch. 35.00m from culvert near enchakkal.	1.50	Completed
23	SDRF- 2018-19: Rectification works for the Manickamangalam branch canal of Avanamcode LIS near ch. 60.00m from culvert near enchakkal.	1.50	Completed
24	SDRF- 2018-19: Rectification works for the Manickamangalam branch canal of Avanamcode LIS near ch. 85.00m from culvert near enchakkal.	1.50	Completed
25	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 20.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
26	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 40.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 60.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 85.00 m from Nedumbassery Police station towards Nayathode.	' 1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 105.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 120.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 150.00 m from Nedumbassery Police station towards Nayathode. SDRF-2018-19: Rectification work to A	1.50	Completed
i	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 165.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 190.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 215.00 m from Nedumbassery Police station towards Nayathode.	1.50	Completed
	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 20.00 m from Nedumbassery Police station towards Airport. SDRF-2018-19: Rectification work to Avanamcode LIS	1.50	Completed
F	SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch 40.00 m from Nedumbassery Police station towards Airport. SDRF-2018-19: Rectification work to Avanamcode LIS main canal near ch	1.50	Completed
<u> </u>	50.00 m from Nedumbassery Police station towards Airport. 50RF-2018-19: Rectification work to Avanamcode LIS main canal near ch	1.50	Completed
—-f°	5.00 m nom Nedumbassery Police station towards Airport.	1.50	Completed
<u> </u>	SDRF-2018-19: Rectification workfor the VCB in Pullapadashekharam in Aukkannoor Panchyat.	1.50	Agt .executed
r	Jrgent rectification work of Kannamkuzhisseri branch canal in Parakkadavu no.1 LIS Jrgent rectification work, of Kuttadam Padamanati and 1500	1.50	Completed
P	Urgent rectification work of Kuttadam Padam west near ch.500m Parakkadavu no.1 LIS Urgent rectification work of Kuttadam Padam west near ch.605m	1.50	Completed
I^r	arakkadavu no.1 LIS Jrgent rectification work of Kuttadam Padam west near ch.605m	1.50	Completed
3 P	arakkadavu no. 1 LIS	1.50	Completed

• 2

ji ka	····		
44	Urgent rectification work of Kuttadam Padam west near ch.750m Parakkadavu no.1 LIS	1.50	Completed
45	Parakkadavu no.1 LIS	1.50	Completed
46	Parakkadavu no.1 LIS	1.50	Completed
47	Parakkadavu no.1 LIS	1.50	Completed
48	Parakkadavu no.1 LIS	1.50	Completed
49	Parakkadavu no.1 LIS	1.50	Completed
50	Parakkadavu no.1 LIS	1.50	Completed
51	Urgent rectification work of Parambissery branch canal near ch.1300m Parakkadavu no.1 LIS	1.50	Completed
52	Urgent rectification work of Parambissery branch canal near ch. 780 Parakkadavu no.1 LIS	1.50	Completed
53	Urgent rectification work of chettukulam branch canal near ch 140m Parakkadavu no.1 LIS	1.50	Completed
54	Urgent rectification work of chettukulam branch canal near ch.355 Parakkadavu no.1 LIS	1.50	Completed
55	Urgent rectification work of chettukulam branch canal near ch.570 Parakkadavu no.1 LIS	1.50	Completed
56	Urgent rectification work of chettukulam branch canal near ch.785 Parakkadavu no.1 LIS	1.50	Completed
57	Urgent rectification work of Chalathiruthy branch canal near ch.90 m in Parakkadavu no.2 LIS.	1.50	Completed
58	Urgent rectification work of Chalathiruthy branch canal near ch. 190m in Parakkadavu no.2 L1S.	1.50	Completed
59	Urgent rectification work of Chalathiruthy branch canal near ch.280 m in Parakkadavu no.2 LIS.	1.50	Completed
60	Urgent rectification work of Chalathiruthy branch canal near ch.370m in Parakkadavu no.2 LIS.	1.50	Completed
61	Urgent rectification work of Chalathiruthy branch canal near ch.520m in Parakkadavu no.2 LIS.	1.50	Completed
62	Urgent rectification work of Chalathiruthy branch canal near ch 670m in Parakkadavu no.2 LIS.	1.50	Completed
63	Urgent rectification work of Chalathiruthy branch canal near ch 830m in Parakkadavu no.2 LIS.	1.50	Completed
64	Urgent rectification work of Srambikkan branch canal near ch. 0 in Erayamkudy LIS.	1.50	Completed
65	Urgent rectification work of Srambikkan branch canal near ch. 60 in Erayamkudy LIS.	1.50	Completed
66	Urgent rectification work of Srambikkan branch canal near ch. 120 in Erayamkudy LIS.	1.50	Completed
67	Urgent rectification work of Erayamkudy main canal near ch. 350 in Erayamkudy LIS.	1.50	Completed
68	Urgent rectification work of Erayamkudy main canal near ch.650 in Erayamkudy LIS.	1.50	Completed
69	Urgent rectification work of Elavoor chantha branch canal near ch. 100 in Erayamkudy LIS.	1.50	Completed
70	SDRF-2018-Urgent rectification works Perumthodu near ch.325 in ward No.1 in Parakkadavu Panchayath.	1.50	
71	SRDRF-2018-Urgent rectification works of Perumthodu in ward no 1 in	1.50	Completed
72	Parakkadavu Panchayath near ch. 305m . SDRF-2018 Urgent rectification works of Perumthodu in ward no.1 in		Completed
73	Parakkadavu Panchayath near ch. 285m . SDRF-2018 Urgent rectification works of Perumthodu in ward no.1 in	1.50	Completed
	Parakkadavu Panchayath near ch. 265m.	1.50	Completed

e - 2

`.

74*       "ORF-2018-Urgent rectification works of Perunthodu in ward no.1 in       1.50       Completed         75       Barkkadovu Penchayath near ch. 245m.       1.50       Completed         76       Barkkadovu Penchayath near ch. 25m.       1.50       Completed         78       Barkkadovu Penchayath near ch. 25m.       1.50       Completed         78       BDRF-2018-Urgent Retification works of Perumthodu in ward no.1 in       1.50       Completed         78       SDRF-2018-Urgent Retification works of Perumthodu in ward no.1 in       1.50       Completed         79       SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         79       SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         70       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         80       Dirgent rectification works of Karthikakulam canal near       1.50       Agt Executed         81       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         82       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         83       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed		1		4
SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           75         Darakiadavi Panchayahi near ch.25m.         1.50         Completed           76         SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           76         SDRF-2018-Urgent Rectification works of Perumthodu in ward no.1 in         1.50         Completed           78         SDRF-2018-Urgent Rectification works of Perumthodu in ward no.1 in         1.50         Completed           78         SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           79         SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           79         SDRF-2018-Urgent rectification works of Karthikakulam canal near ch.3275 in         1.50         Agt Executed           80         Urgent rectification works of Karthikakulam canal near ch.3415         1.50         Agt Executed           81         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           82         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           83         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed				,
SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           75         Daradyadawi Punchayatin near ch.25m.         1.50         Completed           76         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           76         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           78         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           78         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           79         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           79         DRF-2018-Urgent rectification works of Ferumthodu in ward no.1 in         1.50         Agt Executed           80         Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           81         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           82         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           83         SDRF-2018-Urgent rectification works of Tharimola Valiya Kulam branch         15.00         Completed           84	17	DRF-2018-Urgent rectification works of Perumthodu in ward no 1 in		
76         BDRF-2018 Update and Rectification works of Perumthodu in ward no.1 in         1.50         Completed           77         Parakkadawa Panchayata near ch.205m.         1.50         Completed           77         Parakkadawa Panchayata near ch.205m.         1.50         Completed           78         DRF-2018 Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           78         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           79         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Completed           79         DRF-2018-Urgent rectification works of Perumthodu in ward no.1 in         1.50         Agt Executed           80         Urgent rectification works of Farthikakulam canal near ch.3275 in         1.50         Agt Executed           81         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           82         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           83         SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch         15.00         Completed           84         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           85 <td>·  </td> <td><u>i u u u kauavu Fancilavain near ch. 745m</u></td> <td>1.50</td> <td>Completed</td>	·	<u>i u u u kauavu Fancilavain near ch. 745m</u>	1.50	Completed
16       Distriction works of Perumthodu in ward no.1 in       1.50       Completed         7       BarkZadawu Panchayati naar ch.205m.       11.50       Completed         78       BDRF-2018-Urgent Rectification works of Perumthodu in ward no.1 in       1.50       Completed         78       BDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         79       BDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         79       BDRF-2018-Urgent rectification works of Karthikakulam canal near ch.3275 in       1.50       Agt Executed         80       Drepent rectification works of Karthikakulam canal near       1.50       Agt Executed         81       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         82       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         83       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       6.30       Completed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         86       SDRF-2018-Urgent rectification works of Kathikakulam canal from			1.50	Completed
77       SDRF-2018-Urgent Rectification works of Perumthodu in ward no.1 in       1.50       Completed         78       SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         79       SDRF_2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         79       Parakkadavu Panchyayth near Ch.165m.       1.50       Agt Executed         80       Urgent rectification works of Karthikakulam canal near ch.3275 in       1.50       Agt Executed         81       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         82       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         83       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       15.00       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         87       SDRF-2018-Urgent rectification works of Karthikakuam canal near       1.50       Agt Executed         88       SDRF-2018-Urgent rectification works of T	7	<u> </u>	1.50	
78       SDRF-2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         79       SDRF_2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         80       Drgent rectification works of Karthikakularn canal near ch.3275 in       1.50       Agt Executed         81       hb310m in Parakkadavu no.2 LIS       Agt Executed       1.50       Agt Executed         82       SDRF-2018-Urgent rectification works of Karthikakularn canal near       1.50       Agt Executed         83       SDRF-2018-Urgent rectification works of Karthikakularn canal near       1.50       Agt Executed         83       SDRF-2018-Urgent rectification works of Karthikakularn canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       15.00       Completed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         86       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       5.10       Completed         87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       5.10       Completed         89       SDRF-2018-Urgent re	7	<sup>7</sup> SDRF-2018-Urgent Retification works of Perumthody in work	+	
79       SDRF 2018-Urgent rectification works of Perumthodu in ward no.1 in       1.50       Completed         80       Urgent rectification works of Karthikakulam canal near ch.3275 in       1.50       Agt Executed         81       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         82       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         83       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       15.00       Completed         85       SDRF-2018-Urgent rectification works of Karthikakulam canal rear       1.50       Agt Executed         86       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Completed         87       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       5.10       Completed       5.1	7	SDRF-2018-Urgent rectification works of Perumthody in word	1.50	Completed
Box         Urgent rectification works of Karthikakulam canal near ch.3275 in Parakkadavu No.2 LIS.         1.50         Agt Executed           80         Dirgent rectification works of Karthikakulam canal near         1.50         Agt Executed           81         DRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           82         DRF 2018 Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           83         DRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           84         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           85         SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.         15.00         Completed           86         SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.         8.30         Completed           87         SDRF-2018-Urgent rectification works of Kachappily smasanam road branch canal in between ch:100m to 850m in Parakkadavu no.2 LIS         5.10         Completed           88         SDRF-2018-Urgent rectification works of Kachappily smasanam road         8.30         Completed           89         SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 250m in 250m i			1.50	Completed
SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           81         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           82         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           83         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           84         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           85         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           85         SDRF-2018-Urgent rectification works of Karthikakulam canal near         1.50         Agt Executed           86         SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch         8.30         Completed           87         SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch         8.30         Completed           88         SDRF-2018-Urgent rectification works of Kachappilly smasanam road         5.10         Completed           89         SDRF-2018-Urgent rectification works of Kachappilly smasanam road         5.10         Completed           89         SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to         5.70         Complet		$\underline{-}$	1.50	Completed
8] SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         8] SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         8] SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         8] SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       15.00       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       8.30       Completed         87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no:21.IS       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to       6.7       Completed         89       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to       6.7       Completed         89       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to       6.7       Completed         90       SDRF-2018-Urgent rectification works of Kannamkuzhisse	80	r a annada vu NO.2 LIS.	1.50	Agt Executed
82       SDRF 2018 Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         83       ch.3380m in Parakkadavu no.2 LIS       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       15.00       Completed         86       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Poovathussery LIS.       8.30       Completed         87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no.2 LIS       5.10       Completed         88       SDRF-2018-Urgent rectification works of Katudam padam east from ch:200m to350n in Parakkadavu No.1 LIS       5.10       Completed         89       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch:       1.5       Completed         90       SDRF-2018-Urgent rectification works of Kamankuzhissery branch canal       13.4       Completed         91       SDRF-2018-Urgent rectification works of Kamankuzhissery branch canal       13.4       Completed         92	81	SDRF-2018-Urgent rectification works of Karthikakulam canal near ch:3310m in Parakkadayu no:2448		
83       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         84       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       15.00       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         87       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       8.30       Completed         87       SDRF-2018-Urgent rectification works of Kuttadam padam east from       3.40       Completed         88       SDRF-2018-Urgent rectification works to Kadveli canal from ch:3100m to       6.7       Completed         89       SDRF-2018-Urgent rectification works to Frayamkudy main canal from Ch:       1.5       Completed         90       SDRF-2018-Urgent rectification works to Frayamkudy main canal from Ch:       1.5       Completed         91       SDRF-2018-Urgent rectification works of Marinamkuzhissery branch canal       13.4       Completed         92       <	82	SDRF 2018 Urgent rectification works of Karthikakulam analysis 1. 2014	1.50	Agt Executed
84       SDRF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       15.00       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       15.00       Completed         87       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       8.30       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no.2 LIS       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kaudam padam east from ch:250m to350m in Parakkadavu No.1 LIS       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kauveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       5.10       Completed         90       SDRF-2018-Urgent rectification works of Kauveli canal from ch:3100m to 50 m in Erayamkudy LIS.       1.5       Completed         91       SDRF-2018-Urgent rectification works of Kanamkuzhissery branch canal from ch: 90       1.5       Completed         92       SDRF-2018-Urgent rectification works of Kanamkuzhissery branch canal from ch: 90       1.3.4       Completed         93			1.50	Agt Executed
33       DNF-2018-Urgent rectification works of Karthikakulam canal near       1.50       Agt Executed         85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       15.00       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch       8.30       Completed         87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       8.30       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kachappilly smasanam road       6.7       Completed         90       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to       6.7       Completed         90       SDRF-2018-Urgent rectification works of Erayamkudy main canal from Ch:       1.5       Completed         91       SDRF-2018-Urgent suction pit cleaning of Kurumassery LI Scheme Pump       0.55       Completed         92       SDRF-2018-Urgent rectification works of main canal in between ch:300 to       6.54       Completed         93       SDRF-201	- 60		1.50	Agt Executed
85       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal in between ch:100m to 428m in Poovathussery LIS.       15.00       Completed         86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal near ch:428m to 610m in Poovathussery LIS.       8.30       Completed         87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no:2 LIS       5.10       Completed         88       ch:250m to350m in Parakkadavu No.1 LIS       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kathaup padam east from 3250m in Parakkadavu No.2 LIS       3.40       Completed         90       SDRF-2018-Urgent rectification works of Kathaup padam east from ch:3100m to 3250m in Parakkadavu No.2 LIS       6.7       Completed         91       SDRF-2018-Urgent rectification works of Erayamkudy main canal from Ch: 3250m in Parakkadavu No.2 LIS       1.5       Completed         92       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch: 0 to 75m in Parakkadavu No.2 LIS       3       Completed         95       SDRF-20	84	SDRF-2018-Urgent rectification works of Karthikakulam canal near ch:3345m in Parakkadavu No.2 LIS	1.50	
86       SDRF-2018-Urgent rectification works of Tharamoola Valiya Kulam branch canal near ch:428m to 610m in Poovathussery LIS.       8.30       Completed         87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no:2 LIS       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no:2 LIS       5.10       Completed         89       SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to330m in Parakkadavu No.1 LIS       3.40       Completed         90       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       6.7       Completed         91       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Erayamkudy LIS.       1.5       Completed         92       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS       3       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch:0 to 75m (balance work) in Parakkadavu No.2 LIS	85	SDRF-2018-Urgent rectification works of Thormsola Valiante		Agi Executed
87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no:2 LIS       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to:350m in Parakkadavu No.1 LIS       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kuttadam padam east from 3250m in Parakkadavu No.2 LIS       3.40       Completed         90       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       6.7       Completed         90       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Erayamkudy LIS.       1.5       Completed         91       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         92       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works to damaged main canal from ch:0m to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed		canal in between ch:100m to 428m in Poovathussery LIS.	15.00	Completed
87       SDRF-2018-Urgent rectification works of Kachappilly smasanam road branch canal in between ch:100m to 850m in Parakkadavu no:2 LIS       5.10       Completed         88       SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to:350m in Parakkadavu No.1 LIS       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to:350m in Parakkadavu No.1 LIS       3.40       Completed         90       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       6.7       Completed         90       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Erayamkudy LIS.       1.5       Completed         91       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to:320m in Parakkadavu No.1 LIS       13.4       Completed         92       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-19 Urgent rectification works to damaged main canal from ch: 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       2         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       3	86	SDRF-2018-Urgent rectification works of Tharamoola Valiva Kulem have	<del> </del>	
88       SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to350m in Parakkadavu No.1 LIS       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       6.7       Completed         90       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 900 to Ch:950 m in Erayamkudy LIS.       1.5       Completed         91       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Erayamkudy LIS.       0.55       Completed         92       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         93       SDRF-2018-Urgent rectification works of damaged main canal from ch:0 to 75m in Parakkadavu No.2 LIS       3.40       Completed         94       SDRF-2018-Urgent rectification works to damaged main canal from ch:0 to 75m in Parakkadavu No.2 LIS       3.10       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3		canal near ch:428m to 610m in Poovathussery LIS.	8.30	Completed
88       SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to350m in Parakkadavu No.1 LIS       3.40       Completed         89       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       6.7       Completed         90       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 900 to Ch:950 m in Erayamkudy LIS.       1.5       Completed         91       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Erayamkudy LIS.       0.55       Completed         92       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         93       SDRF-2018-Urgent rectification works of damaged main canal from ch:0 to 75m in Parakkadavu No.2 LIS       3.40       Completed         94       SDRF-2018-Urgent rectification works to damaged main canal from ch:0 to 75m in Parakkadavu No.2 LIS       3.10       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3	87	SDRF-2018-Urgent rectification works of Kachappilly smasanam road		
89       SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS       3.40       Completed         90       SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 90 900 to Ch:950 m in Erayamkudy LIS.       1.5       Completed         91       SDRF 2018-Urgent rectification works of Kannamkuzhissery LI Scheme Pump house.       0.55       Completed         92       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to 320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS       3.10       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed		LIS	5.10	Completed
89SDRF-2018-Urgent rectification works of Kaduveli canal from ch:3100m to 3250m in Parakkadavu No.2 LIS6.7Completed90SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Erayamkudy LIS.1.5Completed91SDRF 2018-Urgent suction pit cleaning of Kurumassery LI Scheme Pump house.0.55Completed92SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to 320m in Parakkadavu No.1 LIS13.4Completed93SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS6.54Completed94SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS4.92Completed95SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS3Completed	88	SDRF-2018-Urgent rectification works of Kuttadam padam east from ch:250m to350m in Parakkadayu No 111S	3.40	<u> </u>
90SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch:1.5Completed91SDRF 2018-Urgent suction pit cleaning of Kurumassery LI Scheme Pump house.0.55Completed92SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to 320m in Parakkadavu No.1 LIS13.4Completed93SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS6.54Completed94SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS4.92Completed95SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS3Completed	80			Completed
91       SDRF 2018-Urgent Suction pit cleaning of Kurumassery LI Scheme Pump       0.55       Completed         92       SDRF-2018-Urgent rectification works of Karnamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS       4.92       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 38m in Parakkadavu No.2 LIS       3       Completed		List and a statistical with the statistical sta	6.7	Completed
91SDRF 2018-Urgent Suction pit cleaning of Kurumassery LI Scheme Pump0.55Completed92SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS13.4Completed93SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS6.54Completed94SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS4.92Completed95SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS3Completed	90	SDRF-2018-Urgent rectification works to Erayamkudy main canal from Ch: 900 to Ch:950 m in Frayamkudy LIS	1.6	
92       SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal from ch:50m to320m in Parakkadavu No.1 LIS       13.4       Completed         93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS       4.92       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 105 to 380m in Parakkadavu No.2 LIS       4       4	91	SDRF 2018-Urgent Suction pit cleaning of Kurumassen, LL Scheme D	1.5	Completed
93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS       4.92       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 105 to 380m in Parakkadavu No.2 LIS       3       Completed		house.	0.55	Completed
93       SDRF-2018-Urgent rectification works of main canal in between ch:300 to 375m in Kunnukara LIS       6.54       Completed         94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m to 75m in Parakkadavu No.2 LIS       4.92       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0 to 75m (balance work) in Parakkadavu No.2 LIS       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 105 to 380m in Parakkadavu No.2 LIS       3       Completed	92	SDRF-2018-Urgent rectification works of Kannamkuzhissery branch canal	······································	
94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m       4.92       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch.       3       Completed		Irom ch:50m to320m in Parakkadavu No.1 LIS	13.4	Completed
94       SDRF-2018-Urgent rectification works of damaged main canal from ch:0m       4.92       Completed         95       SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0       3       Completed         96       SDRF-2018-19 Urgent rectification works to damaged main canal from ch.       3       Completed	93	SDRF-2018-Urgent rectification works of main canal in between ch:300 to		<del> </del>
95     SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0     3     Completed       96     SDRF-2018-19 Urgent rectification works to damaged main canal from ch.     3     Completed		575iii in Kunnukara LIS	6.54	Completed
95     SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 0     3     Completed       96     SDRF-2018-19 Urgent rectification works to damaged main canal from ch.     3     Completed	94	SDRF-2018-Urgent rectification works of damaged main canal from ch:0m		
96 SDRF-2018-19 Urgent rectification works to damaged main canal from ch.		to 75m in Parakkadavu No.2 LIS	4.92	Completed
96 SDRF-2018-19 Urgent rectification works to damaged main canal from ch.	~-	SDRF-2018-19 Urgent motification		+
96 SDRF-2018-19 Urgent rectification works to damaged main canal from ch.	95	to 75m (balance work) in Parakkadavu No.2 LIS	3	Completed
96 SDRF-2018-19 Urgent rectification works to damaged main canal from ch. 4.5 Completed			-	Completed
105 to 380m in Parakkadavu No.2 LIS 4.5 Completed	06	SDRF-2018-19 Urgent rectification works to date		<u> </u>
	70	105 to 380m in Parakkadavu No.2 LIS	4.5	Completed
	ľ			

			<u> </u>
	ame of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
	NON PLAN		
	2016-17		
	Annual maintenance of various LI Scheme under M.I.Section, Kalady for 016-17 - including repair works	11.00	Completed
2	Improvements to Neeleeswaram No.1 LI Scheme near Naduvattom church n ward No.1 of Malayattoor Neeleeswaram panchayat	14.00	Completed
	Total	25.00	×.
	2017-18	,	ч,
1	Annual maintenance of Avanamcode No I LI scheme under MI Section, Kalady for 2017-18 including cleaning of suction pit and canals	5.90	Completed
2	Annual maintenance of Manickamangalm, Akkunnu, Piraroor, Chengal Nayathodu, Nettinampilly and Churulichira LI Scheme for 2017 - 18 under Kalady Section including clearing of suction pit and canals	5.10	Completed
3	Annual maintenance of Malayattoor No1 & II and HC LI Schemes under MI Section Kalady for 2017-18 including cleaning of Suction Pit and Canals	5.90	Completed
4	Annual maintenance of Kanjoor Pallikkadvu, Mooryamangalam, Mangattukar and Koonahamkunnu, LI sheme under MI Section, Kalady for 2017-18 including cleaning of suction pit and canals	a 5.20	Completed
	Annual Maintenance of Erayankuudy, Puvathussery, Kurumassery and Paluppuzha LI scheme under MI section, Paravoor for 2017-18 - Including cleaning of Suction pit and Canals	4.30	Completed
	6 Connecting BM Channel to existing C.C Channel at tail end portion of Avanamcode L.I.S	4.60	Completed

			<u></u>
	Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
	Improvements to Mangattukara LI Scheme including raising the side wall of main canal and replacing damaged pump set and allied works in Angamali municipality.	14.00	Completed
3	Extension of Pałupuzha L I Scheme for ward No 16 & 17 of parakkadavu Grama Panchayath.	22.00	Completed
9	Urgent Protection Works to Suction Pit and Leading Channel of Piraroor LI Scheme	5.00	Completed
10	Improvements to Chettikkulam branch canal of Parakkadavu No.1 LI Scheme at tail end portion.	8.00	Completed
11	Annual maintenance of Manappattuchira scheme Neeleeswarm No.1 and No.2 and Kottamam thodu under MI Section Kalady for 2017-18 including of suction pit and canals.	5.80	Completed
12	Urgent protection works to to the suction pit and leading channel of Neeleeswaram LIS in Malayattoor Neeleeswaram GP	7.00	Completed
1	<sup>3</sup> Imporvements to the damaged protection wall of suction pit of Asarithazham LIS connecting Manjalithodu in Karukutty Panchayat	4.00	Completed
_		96.80	
-	2018-19		
-	1 Flood Damages 2018 - Urgent Rectification Works to Damaged Kodinjili L Canal	IS 3.00	Completed
	<ul> <li>Flood Damages 2018 - Urgent Rectification Works to Damaged BM Channel of Avanamcode LIS</li> </ul>	nel 8.00	Completed
	<ul> <li>Flood Damages 2018 - Urgent Rectification Works to Damaged Neeleswar</li> <li>No.1 LIS Canal</li> </ul>	ram 3.00	Completed

	N	_ {
Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
Replacing damaged Delivery Pipe, NRV and Sluice Valve of Manikkamangalam LI Scheme	4.85	Tendered no Response
Flood Damages 2018 - Rectification of Damaged canal of Parakkadavu No.II LI scheme	2.00	Completed
Flood Damages 2018 - Rectification of Damaged main Canal near Ch. 500m FC to Kuttadampadam of Parakkadavu No.I LI Scheme	12.35	Completed
Flood Damages 2018 - Urgent Rectification of Damaged canal from Delivery Cistern of Palupuzha New LI Scheme	5.00	Completed
Annual Maintenance of Sreebhoothapuram, Churulichira, Koonathankunnu, Mangattukara, Kodinjili, and Alakkada L.I Schemes for the Year 2018-19	3.00	completed
Annual Maintenance of Malayattoor No I, Malayattoor No II, Neeleeswaram No I, Neeleeswaram No II, West Harijan Colony and Manappattuchira L I Schemes in Malayattoor Neeleeswaram Panchayat for the Year 2018-19	<sup>1</sup> 6.85	completed
Annual Maintenance of Avanamcode, Manikkamangalam, Nettinampilly, Piraroor, Nayathodu, Kottamamathodu and Akkunnu L.I Schemes for the Year 2018-19	7.00	completed
Flood Damages 2018 - Urgent Rectification Works to Damaged BM Channe of Avanamcode LIS	8.00	completed
Flood Damages 2018 - Urgent Rectification Works to Damaged Neeleswaran No.1 LIS Canal	m 3.00	completed
Annual maintenance of Poovathussery LIS, Erayamkudy LIS, Kurumassery LIS, Palupuzha LIS, Parakkadavu no.1, Parakkadavu no.2 LI Scheme in Parakkadavu panchayat for the year 2018-2019	5.30	completed
Flood Damages 2018 - Rectification of Damaged canal of Parakkadavu No. LI scheme	11 2.00	completed
5 Urgent Rectification of Damaged canal from Delivery Cistern of Palupuzha New LI Scheme	5.00	completed
6 Construction of field channel near ch.0/300 m of Nettinampilly LIS in ward no.6 of Kalady GP.	15.00	Work to be tender

			×
	Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
7	Renovation of new pumphouse of Kottamamthodu LIS in Manjapra GP.	15.00	Work to be tendered
	mprovement to Kaduveli canal (main canal between ch.3290m to 3500m ) of Parakadav No.2 LIS in Parakadav Grama Panchayath	15.00	Work in Progress
	Improvements to sub branch canal of Malayatoor No.1 LIS at Ward No.9 of Malayatoor neeleswaram Grama Panchayath	5.00	Completed
	Improvement to pumphouse of Kurumasery LIS in Parakadav Grama Panchayath	3.50	Tendered
21	Flood 2018- Urgent Electrical Maintanance works Chengal LIS	1.12	Completed
22	Flood 2018- Urgent Electrical Maintanance works Churulichira LIS	1.40	Completed
23	Flood 2018- Urgent Electrical Maintanance works Kottamamthodu LIS	1.68	Not completed
24	Flood 2018- Urgent Electrical Maintanance works Malayatoor No.1 LIS	1.68	Not completed
25	Flood 2018- Urgent Electrical Maintanance works Malayatoor No.2 LIS	1.68	Not completed
26	Flood 2018- Urgent Electrical Maintanance works Malayatoor West LIS	1.12	Not completed
27	Flood 2018- Urgent Electrical Maintanance works Mangatukara LIS	1.68	Not completed
28	Flood 2018- Urgent Electrical Maintanance works Maanikyamangalam LIS	1.68	Not completed
29	Flood 2018- Urgent Electrical Maintanance works Nayathodu LIS	1.12	Not completed
30	Flood 2018- Urgent Electrical Maintanance works Neeleeswaram No.1 LIS	2.24	Not completed
31	Flood 2018- Urgent Electrical Maintanance works Neeleeswaram No.2LIS	2.24	Not completed
32	Flood 2018- Urgent Electrical Maintanance works Netinampally LIS	1.68	Not completed
33	Flood 2018- Urgent Electrical Maintanance works Piraroor LIS	0.84	Not completed
34	Flood 2018- Urgent Electrical Maintanance works Kuramassery LIS	1.87	Completed

			<u> </u>
A	Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
5	Flood 2018- Urgent Electrical Maintanance works Palupuzha LIS	1.58	Completed
6	Flood 2018- Urgent Electrical Maintanance works Parakadavu No.1 LIS	0.85	Completed
7	Flood 2018- Urgent Electrical Maintanance works Parakadavu No.2 LIS	0.85	Completed
	Total	157.16	

#### 2019-20

1	Annual maintenance of Poovathussery LIS, Erayamkudy LIS Kurumassery LIS, Paluppuzha LIS, Parakkadavu No.1 LIS, Parakkadavu No.2 LIS in Parakkadavu Panchayth for the year 2019 -20	6.20	Tendered
2	Annual maintenance of Avanamcode, Manikkamangalam, Nettinampilly, Piraroor, Nayathodu, Kottamamthodu, and Akkunnu LI schemes for the year 2019-20	12.75	Tendered
3	Annual Maintenance of Sreebhoothapuram, Churulichira, Koonathankunnu, Mangattukara, Kodinjili, and Alakkada LI schemes for 2018 - 19	12.60	Tendered
4	Annual Maintenance of Malayattoor No.1, Malayattoor No.II, Neeleswaram No.1, Neeleeswaram No.II, West Harijan Colony and Manappattuchira LISchemes in Malayattoor Neeleeswaram Panchayath for 2019-20	10.90	Tendered
5	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Akkunnu LIS	0.62	Tendered
6	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Avanamcode No.1 LIS	6.38	Tendered
7	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Churulichira No.1 LIS	1.72	Tendered

			to
STA	Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
8	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Koonathamkunnu≹ No.1 LIS	1.46	Tendered
9	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Kottamamthodu No.1 LIS	1.50	Tendered
10	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Malayatoor No.1 LIS (100hp x 2, 5hpx2)	2.64	Tendered
11	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Malayatoor No.2 LIS	2.59	Tendered "
12	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance . contract for motor pump set, stater and electrical accessories at Malayatoor West LIS	1.31	Tendered
13	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Mangaatukara LIS	1.87	Tendered
14	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Manikyamangalam LIS (80hp x2, 5hpx1)	1.56	Tendered
15	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Nayathodu LIS	1.15	Tendered
16	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Neeleeswaram No.1 LIS	3.21	Tendered

			<u>لا</u>
SLA	Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks
	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Neeleeswaram No.3 LIS (100hp x2, 5hpx1)	2.68	Tendered
18	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Netinamppilly LIS	2.10	Tendered
	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance contract for motor pump set, stater and electrical accessories at Piraroor No.1 LIS	1.13	Tendered
20	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Kuttamassery LIS (40hp x1, 45hpx1, 5hpx1)	1.76	Tendered
21	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Parakkadavu No.1 LIS (75hp x2, 40hpx1, 5hpx1)	2.82	Tendered
22	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Parakkadavu No.2 LIS (75hp x2, 5hp, 3hpx1)	2.22	Tendered
23	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Poovathussery (30hp x2, 5hpx1)	1.25	Tendered
24	Maintanance of LIS 2019-20 - Fully Comprehensive Annual Maintenance of Palupuzha (100hp x1, 5hpx1)	1.48	Tendered
	Total	247.05	

				. 12	
Name of Components/Work under each scheme Petails of AS issued for the month (AS No. & Petails of AS issued for the month of the month	SI.No	Financial Allocation (AS Amount in Lakhs)	Details of AS issued for the month(AS No.&date)	Remarks	

• •

2702-00-101-73 Rehabilitation of LI Schemes

	2016-17	· · · · · · · · · · · · · · · · · · ·	
Rehabilitation of L.I.Scheme -2016-2017 in Electrical Wing(Irrigation)Section Kalady under M.I Division Ernakulam	9	G.O.(RT) No.945/2016/WRD dtd 3.12.2016	tendered. No response
Total	9	-	
201	.8-19	<u> </u>	
Urgent rectification works to super passage across Kottamam thodu at tail end portion of Neeleeswaram No.2 LIS	45	AS: GO(RT) No.143/2019/WRD dt.2.3.19	Work to be tendered
TOTAL	45		

м. <u>....</u>М

Name of Components/Work under each schem	e Financial Allocation (AS Amount in Lakhs)	Details of AS issued for the month(AS No.&date)	Remarks
20	19-20		
Construction of field channel for Mangattukara LIS at various places in Angamali Municipality	10.20	GO(Rt)No.819	Work to be tendered
Urgent rectification works to branch canal of Piraroor No.I LIS near Ch.2000Km in ward No.15 of Kalady Grama Panchayath	5.00	- /2019/WRD Dtd.TVM 16.11.2019	Work to be tendered
	15.2		
	18-19		
1Renovation of Partakkattukulam in Ward no.4 of Karukutty GP (1 pond)	18-19	<del>0(RT</del> 40 / /WR 03.	Tendered. No
<ul> <li><sup>1</sup>Renovation of Partakkattukulam in Ward no.4 of Karukutty GP (1 pond)</li> <li><sup>2</sup>Renovation of Pandan chira in Ward no.13 of Kalady GP (1 pond)</li> </ul>	Г <u> </u>	<del>5.60(RT</del> 10.140 / 10.019/WR 1.02.03. 2019	Tendered. No response Work to be tendered
1 Renovation of Partakkattukulam in Ward no.4 of Karukutty GP (1 pond)         2 Renovation of Pandan chira in Ward no.13 of Kalady GP (1 pond)         Total	16 15.68 31.68	AS.GO(RT ) NO.140 / 2019/WR D dt.02.03. 2019	Tendered. No response Work to be tendered
1 Renovation of Partakkattukulam in Ward no.4 of Karukutty GP (1 pond)         2 Renovation of Pandan chira in Ward no.13 of Kalady GP (1 pond)         Total	16 15.68	AS:GO(RT ) NO.140 / 2019/WR D dt.02.03. 2019	Tendered. No response Work to be tendered
1 Renovation of Partakkattukulam in Ward no.4 of Karukutty GP (1 pond)         2 Renovation of Pandan chira in Ward no.13 of Kalady GP (1 pond)         Total	16 15.68 31.68	GO(RT)	Tendered. No response Work to be tendered Work to be tendered

Minor Irrigation Class	5 II (4702-0( 9-20	0-101-82)	
Construction of Paliekkara lift Irrigation Scheme in Paliekkara Quary in ward 20 of Angamaly Municipality 1	45	GO (RT) No.560/2019/ WRD dated 30.07.19	Work to be tendered

B

SI.No	<b>O</b> Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Details of AS issued for the month(AS No.&date)	Remarks	
	2702-00-101-73 Rehabilitation of LI Schemes				

	2702-00-101-73 Reha	IDIIItation of LISche	emes	
	2	016-17		
1	Rehabilitation of L.I.Scheme - Reconstruction of damaged canal near delivery tank and replacing damaged delivery line from the pump house of Kurumassery L.I.Scheme	30	G.O.(RT) 5.945/2016/WR dtd 3.12.2016	Work completed
2	Rehabilitation of L.I.Scheme - Renovation of Pumphouse and costruction of CC Canal in Edavoorkara L.I.Scheme	15	G.O No.945/ D dtd 3	Work completed
3	Rehabilitation of L.I.Scheme -2016-2017 in Electrical Wing(Irrigation)Section Kalady under M.I Division Ernakulam	9		tendered. No response
4	Rehabilitation of L.I.Scheme - Improvements to Main and Branch canals of Parakkadavu No.1 L I Scheme in Parakkadavu Grama Panchayath	15		Work completed
5	Rehabilitation of L.I.Scheme -Reformation of CC canal in between Chainage 0 and 1 Km of Piraroor L1 Scheme in Kalady Grama Panchayath	10		Work completed
	Total '	79		
·	2	017-18		
1	RELIS- Replacing damaged valve and construction of valve house of Manappattuchira Right Bank Canal and improvements to Branch canal at Naduvattom area of Neeleeswaram No.1 L.I.Scheme.	15.00	G.O.(RT) No.616/2017/WRD dtd 20.07.2017	Work completed
2	RELIS- Improvements to canals of Mangattukara L.I.Scheme at Tail end portion in ward, No.2 of Angamaly Municipality	10.00	G.( 0.616/2( 20.0	Work completed
		25.00	ž	
	201	8-19		
1	Urgent rectification works to super passage across Kottamam thodu at tail end portion of Neeleeswaram No.2 LIS	45	AS: GO(RT) No.143/201 9/WRD dt.2.3.19	Work to be tendered
·	TOTAL	45		
	201	9-20	·	
1	Construction of field channel for Mangattukara LIS at various places in Angamali Municipality	10.20	GO(Rt)No.819	Work to be tendered
2	Urgent rectification works to branch canal of Piraroor No.I LIS near Ch.2000Km in ward No.15 of Kalady Grama Panchayath	5.00	/2019/WRD Dtd.TVM 16.11.2019	Work to be tendered

TOTAL

	a 3.		15
Name of Components/Work under each scheme	Financia (AS Ar La	Details of AS issued for the month(AS No.&date)	Remarks
HARITHAKERALAM - REJUVENATIO	N OF PONDS- 4	702-00-101-6	<u>3(P)</u>

<u>2017-18</u>

	Rejuvenation of Ponds (12 ponds) Parambi Chira			
		-		
	Attara Chira			] (
	Parookkaran Chira			
	Parakkattu Kulam	-4	ļ	
1	Poonchira Kulam	-		
*	Ellichira Kulam	7.60		1 1
	Town Kulam	-	j	
	Maniyan Kulam	- ·		
	Kallan Kulam	-	1	
	Arattupuzha Kulam	4		
	Edikottu Kulam	4	0	
	Thuppan Chira		5.2	
	Rejuvenation of Ponds (16 ponds)		1.12.2017	Completed
	Mularippadom Kulam	-1	1	
	KozhiKulam		ੂ ਦੋ	
	Puthoorpilly Chira	<b>1</b>	974/2017/WRD dt.	1
	Kavunkal Kulam		N N	i i
	Kunnappilly Chira			
ł	Kurava Chira		01	
2	Cheenan Chira	1	172	
- 2 H	Karakkatt Chira	12.00	174	
K	Kollankottu PannaChira	12.00	U,	Completed
	/azhutha Kulam			
	Kannan Kulam	-	] ]	
H	andan Kulam			1
H	Cozhikkattu Kulam Cannattu Kulam		[ ]	
5	bengal Thadu Duth Karana			
	hengal Thodu Pothu Kulam anchayath Kulam		1	
<u> </u>			[	

2018-19

<sup>1</sup> Renovation of Partakkattukulam in Ward no.4 of Karukutty GP (1 pond)	16	Tendered. No
2 Renovation of Pandan chira in Ward no.13 of Kalady GP (1 pond)	15.68	Q A I 6 A A A A A A A A A A A A A A A A A
Total	31.68	

Total

## 2019-20

Renovation of Kundoppadam in Karukutty Panchayath	32.00	GO(RT) 559/2019/WRD dt.30.07.19	Work to be tendered
TOTAL	32.00		

. J.	· , ř		16
Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Details of AS issued for the month(AS No.&date)	Remarks

# 702-00-101-65( Minor Irrigation Class II Schemes under Harithakeralam)

,/02-00-101-05( Million Million	2017-18
1 MI Class II harithakeralam- Rejuvenation of Chalilchira to increase the storagecapacity for improving the irrigation facilities in Chalilpadam	Order No MIDEkm 2016/2495/IA dtd 28.03.2018 of CE I&A TVM.
mothepadam. TOTAL	43

Minor Irrigation Class II (4702-00-101-82) 2019-20							
Construction of Paliekkara lift Irrigation Scheme in Paliekkara Quary in ward 20 of Angamaly Municipality	45	GO (RT) No.560/2019/ WRD dated 30.07.19	Work to be tendered				

	•		•
,	$\mathbf{A}$	1	

SI.No	Name of Components/Work under each scheme	Financial Allocation (AS Amount in Lakhs)	Remarks		
NON PLAN					
	2018-19				
1	Replacing damaged Delivery Pipe, NRV and Sluice Valve of Manikkamangalam LI Scheme	4.85	Tendered no Response		
2	Construction of field channel near ch.0/300 m of Nettinampilly LIS in ward no.6 of Kalady GP.	15.00	Work to be tendered		
3	Renovation of new pumphouse of Kottamamthodu LIS in Manjapra GP.	15.00	Work to be tendered		
	Total	34.85	······································		

 $\overline{II}$ 

۰.

onwall no Brad ma

 $\mathbf{e}_{i}$ 

₹ x

**a**.,

オ