**15 -ാം കേരള നിയമസഭ**

**14 -ാം സമ്മേളനം**

**നക്ഷത്ര ചിഹ്നം ഇല്ലാത്ത ചോദ്യം നം. 3059** **07-10-2025 - ൽ മറുപടിയ്ക്ക്**

**മീനച്ചിലാറിന്റെ സംരക്ഷണം**

| **ചോദ്യം** | | **ഉത്തരം** | |
|---|---|---|---|
| **ശ്രീ. മാണി. സി. കാപ്പൻ** | | **ശ്രീ. റോഷി അഗസ്റ്റിൻ<br>(ജലവിഭവ വകുപ്പ് മന്ത്രി)** | |
| (എ) | പാലാ മണ്ഡലത്തിലെ മീനച്ചിലാറിലെ വിവിധ തടയണകളിൽ അടിഞ്ഞു കൂടിയിട്ടുള്ള മാലിന്യങ്ങൾ നീക്കം ചെയ്യുന്നതിന് സ്വീകരിച്ചിട്ടുള്ള നടപടികൾ എന്തെല്ലാമാണെന്ന് വ്യക്തമാക്കാമോ; | (എ) | പാലാ മണ്ഡലത്തിലെ മീനച്ചിലാറിന് കുറുകെ ആറാം മൈൽ തടയണയിൽ അടിഞ്ഞു കൂടിയിട്ടുള്ള ചെളി/ എക്കൽ എന്നിവ നീക്കം ചെയ്യുന്നതിനായി ലേല നടപടികൾ സ്വീകരിച്ചു വരുന്നു. കളരിയാമാക്കൽ ചെക്ക് ഡാമിന് താഴ് വശമുള്ള ചെളി/എക്കൽ എന്നിവ നീക്കം ചെയ്യുന്ന പ്രവൃത്തി പുരോഗമിച്ചു വരുന്നു. |
| (ബി) | മീനച്ചിലാറിലേയ്ക്ക് എത്തിച്ചേരുന്ന പ്രധാനപ്പെട്ട കൈവഴികളുടെ ഭൂരേഖകൾ പ്രകാരമുള്ള വീതിയും ആഴവും വീണ്ടെടുത്ത് സംരക്ഷിക്കുന്നതിന് സ്വീകരിച്ചിട്ടുള്ള നടപടികൾ വ്യക്തമാക്കാമോ? | (ബി) | മീനച്ചിലാറിന്റെ വിവിധ കൈവഴികളിലെ ഒഴുക്കിന് തടസ്സമായ രീതിയിൽ മൺ തിട്ടകളും തടസ്സങ്ങളും നീക്കം ചെയ്യുന്നതിനുള്ള പ്രവർത്തനങ്ങൾ കൈക്കൊണ്ടു വരുന്നു. ഇതിലൂടെ കൈവഴികളുടെ യഥാർത്ഥ വീതിയും ആഴവും പുനസ്ഥാപിക്കുന്നതിന് സാധിക്കുന്നുണ്ട്. ഇതുമായി ബന്ധപ്പെട്ട് കോട്ടയം ഡിവിഷന്റെ കീഴിൽ ഏറ്റെടുത്ത് നടപ്പിലാക്കിയതും നടപ്പിലാക്കിക്കൊണ്ടിരിക്കുന്നതുമായ പ്രവൃത്തികളുടെ പട്ടിക അനുബന്ധമായി ചേർക്കുന്നു. |

സെക്ഷൻ ഓഫീസർ

അനുബന്ധം

# MI DIVISION, KOTTAYAM

| Sl. No | FY | Name of work | Nature of work Desilting/Side protection /Check Dam | AS Amount (in Lakhs) | Remarks or any other comments |
|---|---|---|---|---|---|
| 1 | 2023-24 | General- Desiltation of thodu in Ramapuram panchayath- Clearing and desilting of Palavely puthuvely thodu in ward no.14 of Ramapuram panchayath | Desilting | 15.00 | Completed |
| 2 | 2021-22 | Urgent Restoration of Vempally Kattachira thodu in ward no 3 of Kanakkari panchayath | Desilting | 5.00 | Completed |
| 3 | 2021-22 | Urgent restoration of Kuzhithodu in ward no.16 of Manjoor panchayath. | Desilting | 8.80 | Completed |
| 4 | 2021-22 | Urgent Restoration of Vempally Valiyathodu in Ward No.10 of Kuravilangad Panchayath | Desilting | 0.93 | Completed |
| 5 | 2025-26 | General- Desilting works to Meenachil Valiyathodu from Idayattu bridge in Mutholy Panchayath | Desilting | 2.50 | Site handed over |
| 6 | 2024-25 | GENERAL-Desiltation work Meenara Thodu Bharananganam -Desiltation work Meenara Thodu in ward no . 11 of Bharananganam Panchayath-General Civil Work | Desilting | 2.00 | Initial level taken and reported Rest of the work will be started next week |
| 7 | 2024-25 | GENERAL-Desilting - Lalam thodu- ward no:7- Ramapuram- Desiltaion works to lalam thodu (from chempakasherry check dam to chittett palam) in ward no : 7 of Ramapuram panchayath-General Civil Work | Desilting | 15.00 | Site Handed over |
| 8 | 2024-25 | GENERAL-Desiltation- Pykathodu- ward 11,12- Meenachil panchayath- Desiltaion works to Pykathodu in ward no: 11, 12 of meenachil panchayath -General Civil Work | Desilting | 4.90 | Site Handed over |
| 9 | 2024-25 | GENERAL-Desiltation - Upstream of Aarattukayam checkdam- Thidanadu | Desilting | 6.40 | work could not be progressed |

| | | | | | |
|---|---|---|---|---|---|
| | | panchayath-Desiltation of Chittar thodu (upstream portion of Aarattukayam checkdam) in ward no. 3 and 13 of Thidanadu Panchayath.-General Civil Work | | | due to heavy rain and heavy flow in thodu |
| 10 | 2024-25 | GENERAL-Desilting-Upstream of Chittattinkara Checkdam- Thidanadu panchayath-Desiltation of chittar thodu (upstream portion of Chittattinkara checkdam) in ward no : 2& 14 of Thidanadu panchayath-General Civil Work | Desilting | 3.50 | work could not be progressed due to heavy rain and heavy flow in thodu |
| 11 | 2024-25 | GENERAL-Desiltation-Arattupuzha- ward no. 3,4-Ramapuram pgt-Desiltation works to Arattupuzha thodu (starting from Rosamishiga road) in ward no: 3,4 of Ramapuram panchayath-General Civil Work | Desilting | 25.00 | site handed over |

സെക്ഷൻ ഓഫീസർ